Form 3160-5 (November 1983) (Fc ierl, 9-331)	UNITED ST DEPARTMENT OF T BUREAU OF LAND	HE INTERIOR	SMIT IN TRIPLICATE her instructions on re- se side)	Contract 129
(Do not use this	IDRY NOTICES AND form for proposals to drill or to Use "APPLICATION FOR PERI	REPORTS ON WI deepen or plug back to a MIT—" for such proposals.)	ELLS lifferent reservoir.	Jicarilla Apache 7. UNIT AGRESMENT NAME
OIL GAS WELL  NAME OF OPERATOR	ОТЯБЕ		<u> </u>	N/A 8. FARM OR LEASE WAME
Apache Corp				Apache
3. ADDRESS OF OPERATOR	ln, Ste. 1900, De	nver. CO 80203	-4519	9. WELL NO. #146
4. LOCATION OF WELL (1 See also space 17 bel At surface 2 1	Report location clearly and in acc	ordance with any State requ	iirements.*	10. FIELD AND POOL, OR WILDCAT Lindrith Gallup Dak. 11. SEC., T., B., M., OR RLW. AND SURVEY OR ARMA
				Sec. 24-T24N-R4W
14. PERMIT NO.	15. ELEVATIONS	(Show whether DF, RT, GR, et	L GR	Rio Arriba NM
16.	Charle A appropriate Box			
CHECK / Appropriate Dox 10 marches 1 table 5 to 100 per / 5				UBNT REPORT OF:
TEST WATER SRUT-OF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) RECO	MULTIPLE COMPLIA ABANDON* CHANGE PLANS DIMPLETION	ETE PR	Completion or Recomp	ALTERING WELL ALTERING CASING ABANDONMENT®  s of multiple completion on Well letion Beport and Log form.) , including estimated date of starting any al depths for all markers and zones perti-
well in t	orporation reques the Gallup format e for this work.	ts permission ion. Attached	please find  DE	CEIVED  CON. DIV.
18. I hereby certify tha	t the foregoing is true hold correct	et Sr. Ope		10/08

W.

\*See Instructions on Reverse Side

Apache #146
SW NE Sec 24-T24N-R4W
Recompletion to Gallup
November 14, 1990

- A. MIRU SU
- B. KILL WELL AS REQUIRED
- C. ND WH & PL EQUIPMENT
- D. NU BOP
- E. TOOH W/ TBG
- F. SET WIFELINE SET TBG RETRIEVABLE BP
  - 1. RU WIRELINE COMPANY
  - 2. RUN GAUGE RING TO 6342'
  - 3. SET HALLIBURTON WSTR-BP @ 6332°
- G. PRESSURE TEST TO 3000 PSI
- H. DUMP BAIL 1 SX SD ON BP

NOTE: Check w/ BP & Wireline company about which type of bailer required. Glass btm w/ blasting cap or Glass btm w/ plunger

## I. PERFORATE

- 1. Correlate and perforate w/ csg gun DIL depths w/ 2 jspf as follows:
  - a) 6238-6258°
  - b) 6266-6274°
  - c) 6278-62867

## J. RD WIRELINE COMPANY

- K. BREAK DOWN PERFS
  - 1. TIH W/ RTTS PKR
  - 2. RU SERVICE COMPANY
  - 3. PUMP ACID W/ BALLS PER ATTACHED RECOMMENDATION
  - 4. TOOH W/ RTTS PKR

## L. FRAC GALLUP PERFS

- 1. RU SERVICE COMPANY
- 2. FRAC GALLUP PER SERVICE COMPANY PROCEDURE
- 3. RD SERVICE COMPANY
- 4. SI PER SERVICE COMPANY RECOMMENDATION
- 5. FLOW BACK UNTIL DEAD

- M. CLEAN OUT SAND & BALLS
- N. RETREIVE BP
- O. TIH W/ PRODUCTION STRING
- P. RU TO SWAB WELL UNTIL CLEAN
- Q. RIG TO RUN PUMP AND RODS
- R. RU PU
- S. RETURN WELL TO PRODUCTION