Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

Expires: March 31, 1993

5. Lease Designation and Serial No.

NM OSSO40-A 6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE Escrito i. Type of Well Oil Well Gas Well 2. Name of Operator Escrito Gallup BCO, Inc.

3. Address and Telephone No. 135 Grant, Santa Fc. NM 8750/ 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) (505) 973-1222 10. Field and Pool, or Exploratory Area Escric Sand 990'FSL + 2090'FEL 11. County or Parish, State 512-T24N- R8W GL= 7192' SEID TURN 111/ CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Change of Plans Recompletion **New Construction** Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* BCO, Inc. requests approval to Plug and Abandon. ME ATTACHED FOR CENDITIONS OF APPROVAL OIL COM. DIV. Senior Field Engineer (This space for Federal or State office use)

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of $\hat{\mathbf{u}}$

or representations as to any matter within its jurisdiction


BCO, Inc.


Escrito Gallup #2 (GI) SE, Sec. 12, T24N, R8VV San Juan County, New Mexico

PLUG AND ABANDONMENT PROCEDURE:

(All cement volumes use 100% excess outside pipe and 50' inside; an 8.3 ppg plugging fluid exceeds the exposed reservoirs' pressure.)

- 1. Install and/or test rig anchors. Prepare blow pit. Comply to all NMOCD, BLM and BCO safety rules and regulations.
- 2. MOL and RUSU. Blow well down; kill with water if necessary. ND wellhead and NU BOP and stripping head; test BOP.
- 3. Release packer at 1000' and POH and tally 2-3/8" tubing (5975'); LD packer.
- 4. Plug #1 (Gallup perfs and top): RIH with open ended tubing to 6112' (or as deep as possible). Pump 20 bbls water down tubing. Mix 50 sxs Class B cement and spot a balance plug from 6112' to 5750'. POH to 4000'. WOC. RIH and tag cement. Pull above cement and circulate well clean. POH to 4300'.
- Plug #2 (Mesaverde top): Mix 85 sxs Class B cement and set a balanced plug from 4300' to 3200' inside casing (annulus squeezed with 225 sxs in 1974, 209 sxs outside - 917' annular void filled). POH with tubing.
- 6. Plug #3 (PC & Ft tops): Pressure test casing to 500#. Perforate 2 holes at 2501'. Establish rate into holes if casing tested. PU 4-1/2" cement retainer and RIH; set at 2450'; pressure test tubing to 1000#; establish rate into squeeze holes. Mix 72 sxs Class B cement and squeeze 62 sxs outside casing from 2501' to 2175' (no excess due to next plug above) and spot 10 sxs cement inside casing. POH with setting tool.
- 7. Plug #4 (OA top): Pressure test casing to 500#. Perforate 2 squeeze holes at 2130'. Establish rate into holes if casing tested. PU 4-1/2" cement retainer and RIH; set at 2080'; establish rate into holes. Mix 66 sxs Class B cement and squeeze 56 sxs outside casing from 2130' to 1948' and spot 10 sxs cement inside casing. POH and LD tubing.
- 8. Plug #5 (Surface): Perforate 2 holes at 265'. Establish circulation out bradenhead valve. Mix 84 sxs Class B cement and pump down 4-1/2" casing, circulate good cement out bradenhead valve. Shut in well and WOC.
- ND BOP and cut off well head below surface casing flange and install P&A marker to BLM specs. RD and MOL. Cut off anchors.
- 10. Restore location per BLM stipulations.





UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE 1235 La Plata Highway Farmington, New Mexico 87401

Amachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 2 Escrifo Gallap

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
- 2. Mike Flaniken with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made (when applicable):
- #1.) Perforate à 2458', Place a cement plus from 2458' to 2/00' inside « outside the casing. (PC Top 2 2408', Fruithand top 22150')
 - 2.) Perforate à 1985', Place a cement plus from 1985' to 1670' inside 2 outside the casing plus 50 Liver feet excess minde the casing a 100 Bexcess outside the cum. (030 Alamo 1720' to 1935')

Office Hours: 7:45 a.m. to 4:30 p.m.

on this plus because of the closeness of the century for the oso Alimo plus.

3.) Perforate 2 294 and circulate cement to the surface. (Nacimiento top-244)

· 'řį.