

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. SF-080658
2. NAME OF OPERATOR Tenneco Oil Company	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 3249, Englewood, CO 80155	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1750' FSL, 1000 FEL "I"	8. FARM OR LEASE NAME Reames Com
14. PERMIT NO.	9. WELL NO. 1E
	10. FIELD AND POOL, OR WILDCAT Basin Dakota
	11. SEC., T., R., OR BLK. AND SURVEY OR AREA Sec. 25, T26N, R6W
15. ELEVATIONS (Show whether SP, ST, or etc.) 6614' GR	12. COUNTY OR PARISH Rio Arriba
	13. STATE NM

RECEIVED

JUN 19 1986

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Tenneco requests permission to workover well for suspected casing leak & casing repair. Please see attached procedures.

18. I hereby certify that the foregoing is true and correct

SIGNED

David Hiett

TITLE Sr. Administrative Analyst

APPROVED

DATE JUN 26 1986

(Leave space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JUN 26 1986

AREA MANAGER
FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side

NMOCCL

5680W/2/JJE

LEASE Reames Com

WELL NO. 1E

CASING:

9-5/8 "OD, 36 LB, K-55 CSG W/ 200 SX

TOC @ surf. HOLE SIZE 12-1/4" DATE: 9/3/80

REMARKS

4-1/2 "OD, 10.5/11.6 LB, K-55 CSG W/ 768 SX

TOC @ 2900'. HOLE SIZE 7-7/8" DATE: 9/17/80

REMARKS DV @ 4411'

"OD, LB, CSG W/ SX

TOC @ . HOLE SIZE DATE:

REMARKS

TUBING:

2-3/8 "OD, 4.7 LB, J-55 GRADE, 8 RD, EUE CPLG

LANDED @ 7160'. SN, PACKER, ETC. @ 7128'

"OD, LB, GRADE, RD, CPLG

LANDED @ . SN, PACKER, ETC.

PUMP RODS ANCHOR

DETAILED PROCEDURE:

1. MIRUSU. Kill well w/1% KCl wtr if necessary. NDWH. NUBOP.
2. Tally out w/2-3/8" tbg. RIH w/4-1/2" RBP and fullbore pkr on 2-3/8" tbg. Set RBP @ 7150'. PU 1 jt and set pkr. PT RBP to 1000 psi. PT backside to 1000 psi or isolate leak. Establish rate and pressure into leak, if found.
3. If no leak is found, POOH w/packer and tbg and go to step 6. *Dump 25x SAND ON RBP*
4. If a leak is found, set pkr 150' above and squeeze w/50 sx. Class B containing 2% CaCl and fluid loss additive sufficient for 200 ml fluid loss. If successful, reverse out around packer and SI w/pressure overnight. If unsuccessful, displace cmt 1 bbl past leak. WOC 3 hours. Resqueeze w/50 sx Class B plus same additives. Reverse out and pressure up overnight.

293

DV @ 4411'

7160
Dakota
Perfs
768-7394

7486

7442

LEASE NAME: Reames Com WELL NUMBER: 1E

5. POOH w/2-3/8" tbg and fullbore packer. RIH w/3 7/8" bit and scraper on 2-3/8" tbg and drill out cement. PT casing to 1000 psi. RIH w/bit and scraper to RBP. POOH w//bit, scraper and 2-3/8" tbg.
6. RIH w/RBP retrieving head on 2-3/8" tbg. Latch RBP and POOH.
7. RIH w/2-3/8" tbg and SN 1 joint off bottom. Land @ \pm 7160'.
8. NDBOP, NUWH. Swab Dakota perfs, if necessary to kick off. RDMOSU.