Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED				
Budget Bur	eau No.	100	04-0135	,
Expires:	March	31,	1993	

BOTTE	O OI EARID III III I GEINEITI	
OUNDBY NO	TICES AND REPORTS ON WELLS	5. Lease Designation and Serial No.
SUNDRY NO	Jicarilla Contract 155	
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		8. If Indian, Allottee or Tribe Name
Use "APPLIC	ATION FOR PERMIT - " for such proposals	
		Jicarilla Apache
	•	7. If Unit or CA, Agreement Designation
1. Type of Well		-
Oil Ges Well Other		8. Well Name and No.
2. Name of Operator	Attention;	Jicarilla Contract 155 25
Amoco Production Company	Patty Haefele	9. API Well No.
3. Address and Telephone No.	ratty riacioic	3003922487
·	. CO 80201 (303) 830-4988	10. Field and Pool, or Exploratory Area
P.O. Box 800, Denver		
4. Location of Well (Footage, Sec., T., R., M., or	Survey Description)	Blanco Mesaverde/Otero Chacra
1080' FSL 1570' F	EL Sec. 30 T 26N R 5W Unit O	11. County or Perish, State
1000 102 1070 1	2001 00 1 2011 11 011	Rio Arriba New Mexico
12. CHECK APPROPR	ATE BOX(s) TO INDICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
577	Abendonment	Change of Plans
Notice of Intent	Recompletion	New Construction
	Plugging Beck	Non-Routine Fracturing
Subsequent Report	Casing Repair	Water Shut-Off
[]	Altering Casing Other Downhole Commingle	Conversion to Injection
Final Abandonment Notice		Dispose Water
		ort results of multiple completion on Well Completion or on Report and Log form.)
		MAR 1 1 1935
14. I hereby certify that the foregoing is true and	correct RRLQ Title Staff Assis	tant Date 02-29-1996
(This space for Federal or State office use)		
Approved by Conditions of approval, if any:	Chief, Lands and Miner	al Resources MAR 7 1996

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious, or fraudulent statements or representations as to any matter within its jurisdiction.

SJOET Well Work Procedure

Wellname:

JICARILLA CONTRACT 155-25

Version:

Date: 27-Feb-96

Budget:

Repair Well Expense

Repair Type: Mill Up Packer

Objectives: Increase gas production by milling up the packer that is set between the Chacra and Maseverde formations at 4100', cleaning out the wellbore to 5300', downhole commingling the production streams and returning the well to production with 2-3/8" tubing landed at 5270'.

Pertinent Information:

Location:

O30 26N 05W,

1080 FSL 1570 FEL

FM: CK, MV

County:

Rio Arriba

API:

3003922487

State:

New Mexico

Engr:

Steve Smethie

Lease:

Indian

Phone: H--(303)770-2180

Well FLAC: 842342

W--(303)830-5892

TD: 5355

PBTD: 5325

Economic Information:

APC WI:

100%

Prod. Before Work: 70 MCFD

Estimated Cost: \$35,000

Anticipated Prod.: 220 MCFD

Payout: 9 Mo

Max Cost-12 Mo. P.O.: \$47,000

PV 15:

\$M

Max Cost PV 15:

\$M

Note: Economics will be run on all projects that have a payout exceeding ONE year.

Formation Tops:

Nacimento:

Menefee:

4600 5096

Ojo Alamo:

2280

Pt Lookout:

Kirtland Shale:

2470

Mancos Shale:

Fruitland:

2615

Gallup:

Pictured

2880

Graneros:

Dakota:

Lewis Shale: Cliff House:

4560

Morrison:

Bradenhead Test Information:

Test Date: 6/9/95

Tubing: 160

Casing: 310

BH: 0

INT

CSG

Time

BH 0

CSG 310

5-min: 10 min:

15 min:

Comments:

Suggested Procedure

- 1. Pull and lay down the 1-1/4" 2.4 #/Ft. J-55, IJ short string that is landed at 3890' on the Chacra side.
- 2. Unseat the seal assembly that is set in the Baker Model F packer at 4100'. Pull and lay down the 2-1/16", 3.4 #/ Ft, J-55, IJ, EUE long string that is landed at 5245' on the Mesaverde side.
- 3. Mill up and pluck the Baker Model F packer that is set at 4100' in 5-1/2", 15.5 #/Ft, K-55 casing. Utilize the air package with the booster compressor.
- 4. Clean out the wellbore to 5300' by running a bit and scraper. Sweep the wellbore clean.
- 5. Trip in the hole with a Mule Shoe, Seating Nipple, and 2-3/8" tubing. Land the tubing at 5270'. Charge the cost of the 2-3/8" tubing to maintenance investment, not to the repair expense.
- 6. Broach the tubing to be sure there are no tight spots. We may want to run a plunger in this wellbore at a later date.
- 7. Swab the well in if necessary and notify the pumper that the well has been returned to production.