

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

Form approved,  
Budget Bureau No. 42-B4424.

5. LEASE DESIGNATION AND SERIAL NO.

Mims No. 1, SF078067

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER Water Injector

2. NAME OF OPERATOR  
Shell Oil Company

3. ADDRESS OF OPERATOR  
1700 Broadway, Denver, Colorado 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

600' FSL & 1984' FWL of Sec. 14,  
T25N, R12W, N.M.P.M., San Juan Co., N.M.

11. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
6422.2' KB

7. UNIT AGREEMENT NAME

Carson Unit

8. FARM OR LEASE NAME

9. WELL NO.

Gov't. 24-14

10. FIELD AND POOL, OR WILDCAT

BISTI

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 14, T25N,  
R12W, NMPM

12. COUNTY OR PARISH 13. STATE

San Juan

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING


ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

See attached abandonment prognosis.



18. I hereby certify that the foregoing is true and correct

SIGNED

*R. Plauty*

TITLE Division Operations Engr.

DATE AUG 18 1977

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

cc: NMO&GCC w/attachment

*OK*

\*See Instructions on Reverse Side

8 5/8"  
110'  
24#



5010'  
9.5#

# Plug and Abandonment

Carson Unit 24-14 W.I.  
Section 14, T 25 N, R 12 W  
San Juan County, New Mexico

## Pertinent Data

TD: 5010' PBTD: 4943'  
8 5/8" Csg. @ 110'

4 1/2" Csg. @ 5010' w/ 150 sax.

7 7/8" Hole

Elevation: 6428.4' K.B.

KB - GL = 8.4'

Permanent Datum = KB

Past and current status: Presently T.A.'d  
Only 4' ML Pay, Was peer injector.

Proposed Work: Plug and Abandon

1. Has Tubing. If tubing is opened, lower to PBTD, load hole with mud. (Add 20 sax aquagel + 1 sack Benes per 100 bbls of mud or 20 sax salt gel per 100 bbls mud).
2. Spot 20 sax Class "G" cement mixed w/1# floccle/sack over perforations and above perforations. Minimum requirements - 100' cement plug above perforations. W.C.C. 12 hrs.
3. Pull tubing.
4. Rig up casing pullers. Determine casing free point.
5. Attempt to shoot and pull casing at free point (theoretical cement top at 4240'). Top of Manco Shale 3838'. Do not spend more than 3 hrs. on attempt to pull casing. If unable to pull any casing go to step 8.
6. If casing is recoverable, place cement plugs by cementing through casing or running tubing inside of csg. as it is pulled. Spot Class "G" cement plugs as follows:
  - a. 150' plug across stub of 4 1/2" casing. (50' in casing, 100' in open hole)
  - b. 200' plug from top of Fruitland Coal at 1100' to 1300'.
  - c. 150' plug across base of Ojo Alamo sand at 240'. (100' below base of sand and 50' above base of sand).
  - d. 100' plug across shoe of 8-5/8" casing (30' in casing, 70' in open hole).
  - e. 10 sack plug at surface.

## 7. Install permanent abandonment marker as follows:

Steel marker at least 4 inches in diameter set in concrete and extending at least 4' above mean ground level. The name and number of the well and its location (Unit letter, section, township and range) shall be welded, stamped, or otherwise permanently engraved into the metal marker.

(Continuation from Step 5)

8. Perforate 4 1/2 " casing w/4 JSPF as follows:
- Fruitland Coal - Pictures Cliffs interval 1165' to 1166'.
  - Below Ojo Alamo sand from 340' to 342'.
9. Run tubing, spot a 50 sack Class "G" cement plug from 1165' to 525'.
10. Pull tubing to  $\pm 400'$ , close bradenhead, displace 20 sax through perforations 1165' to 1166'. WOC 2 hours.
11. Pull tubing to perforations 340' to 341'.
12. Load 4 1/2 " casing with cement ( $\pm$  30 sax) and pull tubing. With bradenhead open, displace 20 sax cement through perforations 340' to 341'.
13. Spot 10 sack plug at surface.
14. Install abandonment marker as outlined in step 7.

COC:maf

J. A. Stanzione