

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.
Mims No. 1
SF 078067
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME Carson Unit	
2. NAME OF OPERATOR Shell Oil Company		8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80202		9. WELL NO. 34-14	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 1980 FEL of Sec. 14, T25N, R12W, N.M.P.M. San Juan Co., N.M.		10. FIELD AND POOL, OR WILDCAT Bisti	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA T25N, R12W	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6418.3' K.B.		12. COUNTY OR PARISH San Juan	
		13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL


CHANGE PLANS

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See attached Abandonment Prognosis.



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Div. Opers. Engr.

DATE

OCT 06 1975

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Prognosis
Plug and Abandonment
Carson Unit 34-14
Section 14, T25 N, R 12W
San Juan County, New Mexico

Pertinent Data

TD: 5005 PBD: -
8-5/8" Csg. @ 104
4-1/2" Csg. @ 4999 w/ 150sax. with 4% gel
7-7/8" Hole

Elevation: 6418
KB - GL = 9
Permanent Datum = KB
Past and current status: Presently TAD
Completed 2-10-58. Flowed 240 BOD, 72 MCF/D gas.

Proposed Work: Plug and Abandon

1. Pull equipment. If tubing is openended, lower to PBD, load hole with mud. (Add 20 sax aquagel + 1 sack Benes per 100 bbls of mud or 20 sax salt gel per 100 bbls mud).
2. Spot 20 sax Class "G" cement mixed w/1# flocele/sack over perforations and above perforations. Minimum requirements - 100' cement plug above perforations.
3. Pull tubing.
4. Rig up casing pullers.
5. Attempt to shoot and pull casing at \pm 3500'. (theoretical cement top at 3999. Top of Mancos Shale 3860. If unable to pull any casing, go to step 8.
6. If casing is recovered, run tubing OE and spot Class "G" cement plugs as follows:
 - a. 150' plug across stub of 4-1/2" casing. (50' in casing, 100' in open hole)
 - b. 200' plug from top of Fruitland Coal at 1160 to 1360.
 - c. 150' plug across base of Ojo Alamo sand at 260. (100' below base of sand and 50' above base of sand).
 - d. 100' plug across shoe of 8-5/8" casing. (30' in casing, 70' in open hole).
 - e. 10 sack plug at surface.

4870

4890

4903

4910

4915

4920

4931

4941

4951

4962

4968

4981

4 1/2" to
4999

TD = 5005

7. Install permanent abandonment marker as follows:

Steel marker at least 4 inches in diameter set in concrete and extending at least 4' above mean ground level. The name and number of the well and its location (Unit letter, section, township and range) shall be welded, stamped, or otherwise permanently engraved into the metal marker.

8. Perforate 4-1/2" casing w/4 JSPF as follows:

- a. Fruitland Coal - Pictures Cliffs interval 1200 to 1201.
- b. Below Ojo Alamo sand from 360 to 361.

9. Run tubing, spot a 50 sack (10.3 bbls, 630' in 4-1/2" casing) Class "G" cement plug from 1200 to 570.


10. Pull tubing to $\pm 400'$, close bradenhead, displace 20 sax through perforations 1200 to 1201. WOC 2 hours.

11. Pull tubing to perforations 360 to 361.

12. Load 4-1/2" casing with cement (\pm 35 sax) and pull tubing. With bradenhead open, displace 20 sax cement through perforations 360 to 361.

13. Spot 10 sack plug at surface.

14. Install abandonment marker as outlined in step 7.


J. A. Stanzione