

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

MIMS No. 1
SF 078067

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Shell Oil Company

3. ADDRESS OF OPERATOR

1700 Broadway, Denver, Colorado 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface
660.1' FSL & 660.5' FWL of Sec. 14
T25N, R12W NMPM, San Juan Co., N.M.

7. UNIT AGREEMENT NAME

Carson Unit

8. FARM OR LEASE NAME

9. WELL NO.

14-14

10. FIELD AND POOL, OR WILDCAT

Bisti

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

T25N, R12W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6365.6' K.B.

12. COUNTY OR PARISH

San Juan

13. STATE

N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See attached Abandonment Prognosis.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Div. Ops. Engr.

DATE OCT 06 1975

(This space for Federal or State office use)


APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side



Prognosis
Plug and Abandonment
Carson Unit 14-14
Section 14, T25 N, R12 W
San Juan County, New Mexico

Pertinent Data

8-5/8"
103

TD: 4960 PBSD: -
8-5/8" Csg. @ 103
4-1/2" Csg. @ 4956 w/ 150sax. 4% gel
7-7/8" Hole

Elevation: 6366
KB - GL = 9
Permanent Datum = K.B.
Past and current status: T.A. Shut in 1965
Initial prod. 812 BO, 2 BW, 104 MCF

Proposed Work: Plug and Abandon

1. Pull equipment. If tubing is opened, lower to PBSD, load hole with mud. (Add 20 sax aquagel + 1 sack Benes per 100 bbls of mud or 20 sax salt gel per 100 bbls mud).
2. Spot 20 sax Class "G" cement mixed w/1# flocele/sack over perforations and above perforations. Minimum requirements - 100' cement plug above perforations. WOC 12 hrs
3. Pull tubing.
4. Rig up casing pullers.
5. Attempt to shoot and pull casing at \pm 3500'. (theoretical cement top at 4130. Top of Mancos Shale 3802. If unable to pull any casing, go to step 8.
6. If casing is recovered, run tubing OE and spot Class "G" cement plugs as follows:
 - a. 150' plug across stub of 4-1/2" casing. (50' in casing, 100' in open hole)
 - b. 200' plug from top of Fruitland Coal at 1100 to 1300.
 - c. ~~150' plug across base of Ojo Alamo sand at~~
~~----- (100' below base of sand and 50'~~
~~above base of sand).~~
 - *d. 240' plug across shoe of 8-5/8" casing. (30' in casing, 210' in open hole).
 - e. 10 sack plug at surface.

4857-65

4868-72

4877-87

4898-909

4915-27

4-1/2" @
4956

7. Install permanent abandonment marker as follows:

Steel marker at least 4 inches in diameter set in concrete and extending at least 4' above mean ground level. The name and number of the well and its location (Unit letter, section, township and range) shall be welded, stamped, or otherwise permanently engraved into the metal marker.

8. Perforate 4-1/2" casing w/4 JSPF as follows:

- a. Fruitland Coal - Pictures Cliffs interval 1140 to 1141.
- b. Below Ojo Alamo sand from 310 to 311.

9. Run tubing, spot a 50 sack (10.3 bbls, 630' in 4-1/2" casing) Class "G" cement plug from 1140 to 510.


10. Pull tubing to $\pm 400'$, close bradenhead, displace 20 sax through perforations 1140 to 1141. WOC hours.

11. Pull tubing to perforations 310 to 311.

12. Load 4-1/2" casing with cement (\pm 35 sax) and pull tubing. With bradenhead open, displace 20 sax cement through perforations 310 to 311.

13. Spot 10 sack plug at surface.

14. Install abandonment marker as outlined in step 7.


J. A. Stanzione