
Form 9-831 a (Feb. 1951)

(SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa		Fe,	N.	î.
Lease No	SF	0780	<b>367</b>		
Unit Cs	urs c	n Ur	iit		



## SUNDRY NOTICES AND REPORTS ON WELLS

	RILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CH	IANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACID	ZING
	ST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING.	
	-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR RE	PAIR
•	IOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
•	ILL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO AB	ANDON WELL		
	(INDICATE ABOVE BY CHECK MARK	K NATURE OF REPORT, NOTICE, OR OTHER DATA)	
		December 29	, 19 <b>60</b>
Carson Uni	t	a 200 line and 460 ft from (EX) 15	ne of sec 11
		$\begin{bmatrix} \mathbf{R} \\ \mathbf{S} \end{bmatrix}$ line and $\begin{bmatrix} 460 \\ \mathbf{W} \end{bmatrix}$ line and $\begin{bmatrix} \mathbf{R} \\ \mathbf{W} \end{bmatrix}$	TELE
(½ Sec. and Sec. No.)		(Range) (Meridian)	Coll H
isti - Gallup		n Juan New Mex.	dill
(Field)	(County	or Subdivision) (State or Fe	rritory)
	elly Bushing managementabove sea le	1: 4000 (:	JAN9 1961
he elevation of the <b>i</b>	encus de la	evel is _QXXX_ it.	DIL COS.
	DETA	ILS OF WORK	
			UIST, 3
		ince watchte and langths of proposed casings, indice	te hudding jobs, cemer
	ing points, and all	izes, weights, and lengths of proposed casings; indica other important proposed work)	te hudding jobs, come
ditioning Summer	ing points, and all	other important proposed work)	
ditioning Summar	ing points, and all  Y  Ne bridge plug at 3	3489', squeeze tool at 3424' -	formation w
nditioning Summar 1-60 Set drillab net break d	ing points, and all I'm lie bridge plug at 3 iown at 2000 pai, pa	other important proposed work)	formation w
nditioning Summar 1-60 Set drillab net break d	ing points, and all the bridge plug at 3 lown at 2000 pai, pu	3489°, squeeze tool at 3424° - ulled squeeze tool, pressure t	formation we tested to 3000
nditioning Summar -60 Set drillab net break d pei - ne br -60 Drilled bri	ing points, and all its bridge plug at 3 lown at 2000 pai, pa reak-down. idge plug at 3489*	3489', squeeze tool at 3424' -	formation we tested to 3000
nditioning Summar -60 Set drillab net break d pei - ne br -60 Drilled bri	ing points, and all its bridge plug at 3 lown at 2000 pai, pa reak-down. idge plug at 3489*	3489', squeeze tool at 3424' - ulled squeeze tool, pressure tool and pushed plug to 3740'. Ran	formation we tested to 3000 packer - four
nditioning Summar 1-60 Set drillab net break d pai - ne br 1-60 Drilled bri leak in cas	le bridge plug at 3 com at 2000 pai, pareak-down.  Idge plug at 3489 com 3518 to 3527.	3489°, squeeze toel at 3424° - ulled squeeze toel, pressure tand pushed plug to 3740°. Ran heidae plug at 3589°, squeeze	formation we tested to 3000 packer - four tool at 3456
nditioning Summar 1-60 Set drillab net break d psi - ne br 1-60 Drilled bri leak in cas 1-60 Pulled pack	le bridge plug at 3 lown at 2000 pai, pureak-down. ldge plug at 3489° aing 3518 to 3527.	3489°, squeeze toel at 3424° - ulled squeeze toel, pressure t and pushed plug to 3740°. Ran bridge plug at 3589°, squeeze acuseze tool - no leak. Squeeze	formation we tested to 3000 packer - four tool at 3456 ged interval
nditioning Summar 1-60 Set drillab net break d pei - ne br 1-60 Drilled bri leak in cas 1-60 Pulled pack Pressure to	le bridge plug at 3 lown at 2000 pai, pureak-down. dge plug at 3489 sing 3518 to 3527. ter, set drillable seted casing above set the 150 anche comes	3489°, squeeze toel at 3424° - ulled squeeze toel, pressure t and pushed plug to 3740°. Ran bridge plug at 3589°, squeeze squeeze toel - no leak. Squeeze ant. Pressure dropped from 1600	packer - four tool at 3456 ged interval pai to 800
mditioning Summar -60 Set drillab net break d psi - ne br -60 Drilled bri leak in cas -60 Pulled pack Pressure to 3456-3589 w after tool	le bridge plug at 3 lown at 2000 pai, page ak-down. Idge plug at 3489 lown 3518 to 3527. Idge plug at drillable lower at 3489 lower above at 3489 lower at 3518 to 3527. Idge plug at 3489 lower at 3518 to 3527. Idge plug at 3489 lower at 3518 to 3527. Idge plug at 3489 lower at 3518 to 3527. Idge plug at 3489 lower at 3518 to 3527. Idge plug at 3489 lower at 3518 l	3489°, squeeze toel at 3424° - ulled squeeze toel, pressure t and pushed plug to 3740°. Ran bridge plug at 3589°, squeeze squeeze tool - no leak. Squeeze nt. Pressure dropped from 1600 with 150 sacks coment. Pressu	packer - four tool at 3456 ged interval pai to 800
ditioning Summar -60 Set drillab net break d psi - ne br -60 Drilled bri leak in cas -60 Pulled pack Pressure to 3456-3589 w after tool	le bridge plug at 3 lown at 2000 pai, pureak-down. dge plug at 3489 sing 3518 to 3527. ter, set drillable seted casing above set the 150 anche comes	3489°, squeeze toel at 3424° - ulled squeeze toel, pressure t and pushed plug to 3740°. Ran bridge plug at 3589°, squeeze squeeze tool - no leak. Squeeze nt. Pressure dropped from 1600 with 150 sacks coment. Pressu	packer - four tool at 3456 ged interval pai to 800
ditioning Summar -60 Set drillab net break d psi - ne br -60 Drilled bri leak in cas -60 Pulled pack Pressure to 3456-3589 w after tool	le bridge plug at 3 lown at 2000 pai, page ak-down. Idge plug at 3489 lown 3518 to 3527. Idge plug at drillable lower at 3489 lower above at 3489 lower at 3518 to 3527. Idge plug at 3489 lower at 3518 to 3527. Idge plug at 3489 lower at 3518 to 3527. Idge plug at 3489 lower at 3518 to 3527. Idge plug at 3489 lower at 3518 to 3527. Idge plug at 3489 lower at 3518 l	3489°, squeeze toel at 3424° - ulled squeeze toel, pressure t and pushed plug to 3740°. Ran bridge plug at 3589°, squeeze squeeze tool - no leak. Squeeze nt. Pressure dropped from 1600 with 150 sacks coment. Pressure ol cleared.	packer - four toel at 3456 med interval opsi to 800 ure dropped f:
mditioning Summar 1-60 Set drillab net break d pei - ne br 1-60 Drilled bri leak in cas 1-60 Pulled pack Pressure to 3456-3589 w after tool 1900 psi to	ing points, and all the legal of the legal o	3489°, squeeze toel at 3424° - ulled squeeze toel, pressure t and pushed plug to 3740°. Ran bridge plug at 3589°, squeeze squeeze tool - no leak. Squeeze nt. Pressure dropped from 1600 with 150 sacks cament. Pressu ol cleared.  (Con	formation we tested to 3000 packer - four tool at 3456 ged interval 0 psi to 800 ure dropped for tinued Over)
ditioning Summar -60 Set drillab net break d psi - ne br -60 Drilled bri leak in cas -60 Pulled pack Pressure to 3456-3589 w after tool 1900 psi to	ing points, and all the legal of the legal o	3489°, squeeze toel at 3424° - ulled squeeze toel, pressure t and pushed plug to 3740°. Ran bridge plug at 3589°, squeeze squeeze tool - no leak. Squeeze nt. Pressure dropped from 1600 with 150 sacks coment. Pressure ol cleared.	formation we tested to 3000 packer - four tool at 3456 ged interval 0 psi to 800 ure dropped for tinued Over)
ditioning Summar  -60 Set drillab  net break d  psi - ne br  -60 Drilled bri  leak in cas  -60 Pulled pack  Pressure te  3456-3589 v  after tool  1900 psi to	ing points, and all the legislation at 2000 pai, paireak-down.  Idge plug at 3489 in 3518 to 3527.  Idge plug at 3489 in 3527.  Idge p	3489°, squeeze toel at 3424° - ulled squeeze toel, pressure t and pushed plug to 3740°. Ran bridge plug at 3589°, squeeze squeeze tool - no leak. Squeeze nt. Pressure dropped from 1600 with 150 sacks cament. Pressu ol cleared.  (Continuously the Geological Survey before operations	packer - four tool at 3456 ged interval opsi to 800 ure dropped fit tinued Over)
ditioning Summar  -60 Set drillab  net break d  psi - ne br  -60 Drilled bri  leak in cas  -60 Pulled pack  Pressure te  3456-3589 v  after tool  1900 psi to	ing points, and all the legal of the legal o	3489', squeeze toel at 3424' - ulled squeeze toel, pressure t and pushed plug to 3740'. Ran bridge plug at 3589', squeeze squeeze toel - no leak. Squeeze nt. Pressure dropped from 1600 with 150 sacks cament. Pressure el cleared.  (Continuating by the Geological Survey before operations	packer - four toel at 3456 ked interval 0 psi to 800 ure dropped f: tinued Over)
ditioning Summar  -60 Set drillab  net break d  pai - ne br  -60 Drilled bri  leak in cas  -60 Pulled pack  Pressure te  3456-3589 w  after tool  1900 psi to	le bridge plug at 3 lown at 2000 pai, pureak-down. Idge plug at 3489 loing 3518 to 3527. Idge plug at 3489 loing 3518 loing 351	3489°, squeeze tool at 3424° - ulled squeeze tool, pressure to and pushed plug to 3740°. Ran bridge plug at 3589°, squeeze squeeze tool - no leak. Squeeze not. Pressure dropped from 1600 with 150 sacks cament. Pressure ol cleared.  (Continuity of the Geological Survey before operations Original Si	packer - four toel at 3456 ged interval pai to 800 ure dropped f: tinued Over)
ditioning Summar  -60 Set drillab  net break d  psi - ne br  -60 Drilled bri  leak in cas  -60 Pulled pack  Pressure te  3456-3589 v  after tool  1900 psi to	le bridge plug at 3 lown at 2000 pai, pureak-down. Idge plug at 3489 loing 3518 to 3527. Idge plug at 3489 loing 3518 loing 351	3489', squeeze toel at 3424' - ulled squeeze toel, pressure t and pushed plug to 3740'. Ran bridge plug at 3589', squeeze squeeze toel - no leak. Squeeze nt. Pressure dropped from 1600 with 150 sacks cament. Pressure el cleared.  (Continuating by the Geological Survey before operations	packer - four toel at 3456 ged interval pai to 800 ure dropped f: tinued Over)
ditioning Summar  -60 Set drillab  net break d  pai - ne br  -60 Drilled bri  leak in cas  -60 Pulled pack  Pressure to  3456-3589 w  after tool  1900 psi to  I understand that this plan  company Shell G	le bridge plug at 3 lown at 2000 pai, pureak-down. Idge plug at 3489 loing 3518 to 3527. Idge plug at 3489 loing 3518 loing 351	3489°, squeeze tool at 3424° - ulled squeeze tool, pressure to and pushed plug to 3740°. Ran bridge plug at 3589°, squeeze squeeze tool - no leak. Squeeze not. Pressure dropped from 1600 with 150 sacks cament. Pressure ol cleared.  (Continuity of the Geological Survey before operations Original Si	packer - four toel at 3456 zed interval 0 pai to 800 ure dropped f: tinued Over) may be commenced.

- 12- 2-60 Pulled squeeze tool, located top of cement at 3527 (bettom of split). Set squeeze tool at 3425. Staged in 100 sacks cement, pressure increased from 1000 psi to 3500 psi.
- 12- 3-60 Pulled squeeze tool. Cleaned out cament to 3575°. Pressure tested casing with 1200 psi would not hold pressure. Ran squeeze tool set at 3400°. Staged in 100 sacks cament, pressure increased to 3500 psi on final stage.
- 12-4--5- Cleaned out to 3570 with void space 3530-50. Pressure tested to 1200 psi, 1960 bled to 750 psi in 15 min. Set squeeze tool at 33054 displaced 100 sacks cement, pressure increased to 3500 psi.
- 12-6-60 Cleaned out cement to 3550. Swabbed fluid from 165' to 1495', let stand to 7 hrs., checked fluid level at 1495'. Cleaned out cement to 3662. Drilled 12-13-60 and pushed Bridge plugs to 4845' (Lest circulation at 4830 (perfs 4746-4847) regained circulation).
- 12-14-60 Ran reds and pump en production 2:00 P.M. 12-14-60