UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Not	cices and Reports on Wells		
	*****	5.	Lease Number
			SF-080669
1. Type of Well GAS		6.	If Indian, All. or Tribe Name
		7.	Unit Agreement Name
2. Name of Operator			
RESOURCES AT			
TESCORCES OIL	& GAS COMPANY	_	San Juan 27-4 Unit
2 Address C Phase Vis. of O		8.	
 Address & Phone No. of Opera PO Box 4289, Farmington, NN 		9.	San Juan 27-4 U #13 API Well No.
10 box 4209, rankington, Ni	1 87499 (303) 320-9700	9.	30-039-06992
4. Location of Well, Footage, S		10.	Field and Pool
1800'FNL, 1500'FEL, Sec.20,	T-27-N, $R-4-W$, $NMPM$		Tapacito Pict.Cliffs/
		1.1	Blanco Mesaverde
		11.	County and State Rio Arriba Co, NM
			RIO AIIIDA CO, RM
Final Abandonment 13. Describe Proposed or Comp It is intended to plug an procedure.	Altering Casing Control Other - Control Other		
		20, <i>D</i>	PECELVED S91182 18 PH 1:
			: 17 M
		* * * * * * * * * * * * * * * * * * * *	
14. I hereby certafy that the	e foregoing is true and corr	ect.	
Signed Signy Shall hull	(KLM3) Title Regulatory A	Administrato	r_Date 3/17/99
(This space for Federal or Stat	ce Office use)		
(This space for Federal or State APPROVED BY /S/ Duane W. Sper CONDITION OF APPROVAL, if any:	CerTitle	Date M	AR 25 1999

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

PLUG AND ABANDONMENT PROCEDURE

2-24-99

San Juan Unit 27-4 #13 5330601/5330602

Blanco Mesaverde / Tapacito Pictured Cliffs 1800' FNL, 1500' FEL, Sec. 20, T27N, R4W Rio Arriba County, New Mexico

Project Summary: The San Juan 27-4 Unit No. 13 was completed in 1958 as a dual Mesa Verde / Pictured Cliffs producer. In late 1989 the PC production dropped from 60 MCFD to 0 MCFD. Four years later the Mesa Verde production dropped from 200 MCFD to 0 MCFD. I suspect that the casing failed above the packer in 1989, which killed the PC production. In 1993 it is likely that either the packer or the MV tubing failed resulting in the MV being drowned out. Based on our recent work in the San Juan 27-4 Unit No. 13A, I believe that both zones are very likely damaged beyond repair and that the best course of action is to stop any further water migration by plugging this well. We will swab test the Mesa Verde to confirm that it is damaged.

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

- 1. Prepare blow pit. Comply to all NMOCD, BLM, and BRO&G safety regulations. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with water as necessary.
- 2. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU relief line to flow back tank. Blow well down; kill with water as necessary. ND wellhead and NU BOP and stripping head; test BOP.
- 3. POH with 1-1/4" Pictured Cliffs tubing (3670'). Changeover for 2-3/8" tubing. PU on Mesaverde tubing and release Baker EGJ retrievable packer (see attached information regarding Model EGJ packer). If packer will not release then cut tubing above packer and fish. TOH with 2-3/8" tubing (rubber covered joints from 3612' to 3674'), total tally 5906', LD packer. Inspect 2-3/8" tubing, if necessary LD and pick up workstring. Mesaverde tubing likely has a hole(s). RIH with mill on 2-3/8" tubing to PBTD at 5945', POOH.
- 4. TIH with 2-3/8" tubing and 5-1/2" Full bore packer (SN and 500' of tail-pipe under packer); set packer at 5300' so that bottom of tail pipe is at 5800'. Rig up swab tools and swab Meseverde zone to determine gas and water production. Call Operations Engineer for further instructions. If no gas, then plug well as shown below. POOH with tubing and packer.
- 5. Plug #1 (Mesaverde perforations and top, 5350' 5250'): Set 5-1/2" wireline CIBP at 5350'. TIH with open ended tubing and tag CIBP. Mix 12 sxs Class B cement and spot a balanced plug inside casing above the CIBP to isolate Mesaverde interval. PUH to 3843'.
- 6. Plug #2 (7-5/8" Casing Shoe and Pictured Cliffs perforations, 3843' 3565'): Mix 63 sxs Class B cement and spot a balanced plug in the 5-1/2" liner and 7-5/8" casing to cover casing shoe and to fill perforations. PUH with tubing to 3000' and WOC. TIH and tag cement. Load casing with water and circulate clean. Pressure test casing to 500#. If casing does not test then spot or tag subsequent plug.
- 7. Plug #3 (Fruitland top, 3454' 3354'): Mix 34 sxs Class B cement and spot a balanced plug inside casing to cover Fruitland top. PUH to 3241'.

- 8. Plug #4 (Kirtland and Ojo Alamo tops, 3241' 3060'): Mix 52 sxs Class B cement and spot balanced plug inside casing over Kirtland and Ojo Alamo tops. TOH with tubing.
- 9. Plug #5 (Nacimiento top, 2020' 1920'): Perforate 3 HSC squeeze holes at 2020'. Establish rate into squeeze holes if casing tested. Set 7-5/8" cement retainer at 1970'. Mix 71 sxs Class B cement, squeeze 37 sxs outside 7-5/8" casing and leave 34 sxs inside to cover Nacimiento top. TOH with tubing. If casing did not pressure test previously, then pressure test again to 500 psi. If pressure test fails then perform pump-around test to estimate casing leak depth.
- 10. Plug #5 (10-3/4" casing shoe at 172'): Perforate 3 HSC squeeze holes at 222'. Establish circulation down 7-5/8" casing and out bradenhead. Mix 106 sxs Class B cement and pump down 7-5/8" casing from 222' to surface, circulate good cement out bradenhead. If a casing leak was identified in Step #9 above 222', then utilize a cement retainer at 172'. Shut in well and WOC.
- 11. BOP and cut off wellhead below surface casing. Install P&A marker to comply with regulations. RD, MOL, cut off anchors, and restore location.

Recommended:

Operations Engineer 16/2/Approved:

Kevin Midkiff /

Office - 326-9807 Pager - 564-1653 Drilling Superintendent 3.16.99