UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RE	0.5	137	٠.	r.
T.E.	した	W	F	1.

		BIM	
Sundry Notice	es and Reports on We	lls	
1. Type of Well GAS		DV-12-PM-2:28. FARMINGTON, NN & .	Lease Number SF-079493A If Indian, All. or Tribe Name
2. Name of Operator		7.	Unit Agreement Nam
BURLINGTON	EAS COMPANY		San Juan 27-5 Unit
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 8	Well Name & Number San Juan 27-5 U #1 API Well No.		
4. Location of Well, Footage, Sec. 1650'FSL, 1840'FWL, Sec. 35, T-2	, T, R, M 7-N, R-5-W, NMPM		30-039-20467 Field and Pool Basin Dakota County and State Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO INDIC Type of Submission _X_ Notice of Intent	Type of Ac Abandonment	ction Change of Pl	lans
Subsequent Report	Recompletion Plugging Back Casing Repair	New Construction Non-Routine	Fracturing
Final Abandonment	Casing Repair Altering Casing _ K_ Other - Tubing re	Water Shut o Conversion to epair	orr O Injection
13. Describe Proposed or Complete	ed Operations	<u> </u>	
It is intended to repair the procedure and wellbor	tubing of the subject e diagram.	ect well accordi	ng to the attached
		1111	SEIVED OV 2 0 1937
			CON. DIV.
14. I hereby certify that the for Signed Analy (egoing is true and KLM8) Title Regulato		<u>r</u> Date 11/10/97
(This space for Federal or State Of APPROVED BY	fice use) Title		10V 8 1997
CONDITION OF APPROVAL, if any:		Date	

Tubing Repair Procedure

10/28/97

San Juan 27-5 No. 144 DPNO 44060A Basin Dakota Field 1650' FSL & 1840' FWL. Section 35, T-27-N, R-5-W Rio Arriba county, NM

Project Summary: The San Juan 27-5 No. 144 is a Dakota producer drilled in 1972. This well has loaded up and appears to have scale in the tubing (slickline can not get through). It is possible that the loading problem may be caused by a hole in the casing so we will perform a MIT while on this well. I propose to pull the tubing, replace any bad joints, clean the well out and install plunger lift equipment in order to return the well to production.

- 1. Install and test location rig anchors. Prepare blow pit. Comply to all NMOCD, BLM, and Burlington regulations.
- MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU 2. relief line. Blow down well and kill with 2% KCI water as necessary. ND wellhead and NU BOP.
- 3. Pick up 1-1/2" tubing and RIH to tag PBTD. Tally out of hole with 1-1/2" tubing. Visually inspect the tubing and replace any joints that are corroded or scaled up.
- RIH with a bit and casing scraper (or mill) and clean out to PBTD with air. POOH and RIH with RBP and set at 7500'. Load casing and test to 750 psi. Unload well with air and release RBP,
- If a casing leak is found then stand back the 1-1/2" tubing and pick up a 2-3/8" workstring. Dump 5. 2 sxs of sand on the RBP. Isolate the holes with a packer and establish a pump-in rate and pressure. Notify the Operations Engineer to obtain a squeeze procedure. Squeeze the casing leak according to the prescribed procedure. WOC and drill out cement. Test casing to 750 psi and resqueeze as necessary. Retrieve RBP and lay down workstring.
- RIH with expendable check, 1 jt., SN and 1-1/2" production tubing. Land tubing at approximately 6. 7770'. ND BOP, NU wellhead. Pump off check and blow well in.
- RDMO PU. Turn well to production. Production Operations will set plunger lift. 7.

Recommended:

Operations Engineer

Approval:

Operations Engineer:

Kevin Midkiff

Office: 326-9807

Pager: 564-1653

Home: 324-8596

Production Foreman: Office: 326-9846

Ward Arnold

Pager: 326-8340

Spud-

1st Deliver Elevation.

6607' GL, 6619' KB Workover Swapbed well several times

between 1 4 and 1995

5/95 - Ran : lickline, ran 1-1/2" gauge ring to 7380', 1-1/4" blind box to 7710' (very tight).

Well currently logged off.

San Juan 27-5 Unit No. 1.

Current -- 10/28/97

DPNO: 44060A Basin Dakota

1650' FSL & 1840' FWL

Unit K, Sec. 35, T27N, R05W, Rio Arriba County, NM Lat/Long: 36°31.6580", -107°19.7873"

