

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil gas X well other

2. NAME OF OPERATOR

Tenneco Oil Company

3. ADDRESS OF OPERATOR

720 S. Cola. Blvd., Denver, CO 80222

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 660 FNL & 1980 FEL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

CHANGE ZONES

ABANDON*

(other)

SUBSEQUENT REPORT OF:

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to plug and abandon this well following the procedure prescribed on the attached well-bore schematic.



Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *Carley* Asst. Div. Admin. Manager DATE 8/25/80

CONDITIONS OF APPROVAL, IF ANY:

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

APPROVED

*See Instructions on Reverse Side

SEP 9 1980
Jane Y
JAMES F. SIMS
DISTRICT OIL & GAS SUPERVISOR

LEASE W. O. Berger

WELL NO. #1

9-5/8 "OD, 32.3 LB, H-40 CSG.W/ 245 SX
TOC @ surface

283'

5-1/2 "OD, 14 & 15.5 LB, J-55 CSG.W/ 100 SX
TOC @ ?

DETAILED PROCEDURE

1. MIRUSU.
2. Blow down well.
3. NDWH, NUBOP.
4. Release pkr & TOOH w/tbg.
5. PU cmt retainer & RIH. Set at 5100'.
6. Squeeze Gallup perfs w/100 sxs Class B neat cmt.
7. Pull out of retainer & spot 5 sxs Class B on top.
8. POOH w/tbg.
9. Run Freepoint indicator & cut off csg 300' above freepoint.
10. POOH & lay down casing.
11. RIH w/tbg to csg stub, then POOH spotting the following Class B plugs:

	<u>Formation</u>	<u>Depth</u>	<u>Plug</u>
5122	Csg stub	?	25 sxs
5152	Mesaverde	2300-4250'	550 sxs
5202	PC	1500-1800'	85 sxs
5221	Farmington	700-900'	55 sxs
5260	Surface	0-600'	175 sxs.

12. Install P&A marker.
13. Clean, grade & reseed location.

5381'

5344