UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Well	ls	
	5.	Lease Number SF 080516
1. Type of Well GAS	6.	
	7.	
2. Name of Operator BURLINGTON RESOURCES		San Juan 28-5 Unit
	8.	Well Name & Number San Juan 28-5 U #6
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No. 30-039-0741691-
4. Location of Well, Footage, Sec., T, R, M 1650' FSL, 1650'FWL, Sec. 16, T-28-N, R-5-W	10.	Field and Pool Blanco MV
1030 182, 1030 1M2, 2001 10, 1 20 M, M 3 M	11.	County and State Rio Arriba Co., NM
Recompletion Recompletion Plugging Back	Change of Pl New Construction Non-Routine Water Shut of Conversion to	etion Fracturing off to Injection
DAI DE	CAL DIV.	
14. I hereby certify that the foregoing is true and signed MANY MANAGER (ROBS) Title Regulato	correct.	Date 12/31/97
(This space for Federal or State Office use) APPROVED BY /S/ Duane W. Spencer Title CONDITION OF APPROVAL, if any:	Date	JAN 1 3 1998

San Juan 28-5 Unit #6

Mesaverde 1650'S 1650'W

Unit K, Section 16, T-28-N, R-05-W

Latitude / Longitude: 36° 39.50' / 107° 22.04'

DPNO: 49042A

Tubing Repair Procedure

- Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental 1. regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- 3. Release donut, pick up additional joints of tubing and tag bottom. (Record depth.) TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- 4. If casing requires clean out, TIH with bit and bit sub and CO to PBTD prior to running casing scraper. Roundtrip casing scraper and bit to below preforations. (Do not clean out with casing scraper.) PU above perforations and flow the well naturally, making short trips for clean up when necessary. TOOH.
- 5. TIH with 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom. Rabbit all tubing. CO to PBTD.
- 6. Land tubing near 5780'. ND BOP and NU wellhead. Pump off expendable check. Obtain final pitot gauge up the tubing. If well will not flow on its own, make swab run to seating nipple. If a swab run is not necessary, run a broach on slickline to ensure that the tubing is clear. RD and MOL. Return well to production.

Recommended: Operations Engineer /2-7-97 Approved:

Rob Stanfield

Office - (326-9715)

Home - (327-7646)

Pager - (324-2674)