UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

		10.11-2	1 1.		
S	undry Notices a	nd Reports on	Wells		
		57 Eta =3	F.: 1:4.1	5.	Lease Number SF-079250
l. Type of Well GAS		60		6.	
				7.	Unit Agreement Name
2. Name of Operator	73. 7				
RESOURCE	OIL & GAS	COMPANY		8.	San Juan 28-5 Unit Well Name & Number San Juan 28-5 U #13
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700				9.	API Well No. 30-039-07457
4. Location of Well, Footage, Sec., T, R, M				10.	Field and Pool
890'FSL, 1033'FWL,	Sed.9, T-28-N,	R-5-W, NMPM		11.	Blanco Mesaverde County and State Rio Arriba Co, NM
Type of Submission _X_ Notice of I Subsequent Final Aband	Report	Type of Abandonment Recompletion Plugging Back Casing Repair Altering Casi	New Conve	onstruct outine l Shut of	tion Fracturing Ef
13. Describe Propose It is intended t procedure	o repair the tu		subject well	accordi	ng to the attached
-	,		[D] [
				DEC 1	1 1887 EV
			0[[GREE BREE	Lagy, S
14. I hareby certify Signed Willy	Mhuel Ro				<u>r</u> Date 12/8/97
(This space for Federa APPROVED BY	l or State Offi	.ce use) Title		Date	DEC - 9 1997
CONDITION OF APPROVAL,					

San Juan 28-5 Unit # 13

Mesaverde 890' FSL 1033' FWL

Unit M, Section 9, T-28-N, R-05-W

Latitude / Longitude: 36° 9.62' / 107° 14.74'

DPNO: 49695A

Tubing Repair Procedure

- 1. Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- Release donut, pick up additional joints of tubing and tag bottom. (Record depth.) TOOH with 3. tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- 4. If casing requires clean out, TIH with bit and bit sub and CO to PBTD prior to running casing scraper. Roundtrip casing scraper and bit to below perforations. (Do not clean out with casing scraper.) PU above perforations and flow the well naturally, making short trips for clean up when necessary. TOOH.
- TIH with 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off 5. bottom. Rabbit all tubing. CO to PBTD.
- 6. Land tubing near 5775'. ND BOP and NU wellhead. Pump off expendable check. Obtain final pitot gauge up the tubing. If well will not flow on its own, make swab run to seating nipple. If a swab run is not necessary, run a broach on slickline to ensure that the tubing is clear. RD and MOL. Return well to production.

Recommended: **COTUME!**
Operations Engine

Approved:

R. O. Stanfield, Jr.

Office - (326-9715)

Home - (327-7646)

Pager - (324-2674)