

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

<p>1. Type of Well GAS</p> <p>2. Name of Operator BURLINGTON RESOURCES OIL & GAS COMPANY</p> <p>3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700</p> <p>4. Location of Well, Footage, Sec., T, R, M 1031' FSL 1150' FWL, Sec. 22, T-28-N, R-5-W, NMPM</p>	<p>5. Lease Number SF-079519-A</p> <p>6. If Indian, All. or Tribe Name</p> <p>7. Unit Agreement Name San Juan 28-5 Unit</p> <p>Well Name & Number San Juan 28-5 U#82</p> <p>API Well No. 30-039-20236</p> <p>10. Field and Pool Basin Dakota</p> <p>11. County and State Rio Arriba Co, NM</p>
---	--

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other - tubing repair	

13. Describe Proposed or Completed Operations

It is intended to repair the tubing on the subject well according to the attached procedure.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] (TL8) Title Regulatory Administrator Date 11/5/98
TLW

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD

San Juan 28-5 Unit #82
Basin Dakota
Unit M, Sec. 22, T-28-N, R-5-W
Latitude / Longitude: 36°38.53182' / 107°21.05070'
Recommended Tubing Repair Procedure 10/19/98

Project Notes: This well had its tubing repaired in 3/95. In 9/98, the lease operator ran slickline in the well, but **was unable to retrieve the piston**, believing it to be stuck in scale. When a choke was set in the tubing, the tubing would not blow down, and the casing lost 50 psig in 5 minutes. A hole in the tubing is suspected.

NOTE: ALL DEPTHS ARE MEASURED FROM KB. KB to GL was 10'.

1. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Prior to moving in rig, make one-call and then verify rig anchors and dig pit.
2. MIRU workover rig. NU relief line and blow well down (kill with 2% KCL water only if necessary). ND WH and NU BOP. Test and record operation of BOP rams. Replace any WH valves that do not operate properly. Test secondary seal and install or replace if necessary.
3. **Dakota, 2-3/8", 4.7#, J-55 tubing set at 8041'.** Release donut, pick up additional joints of tubing and tag bottom, recording the depth. PBTD should be at +/- **8090'**. TOOH and stand back 2-3/8" tubing. Visually inspect tubing for corrosion, and replace any bad joints. Check tubing for scale and notify Operations Engineer if it is present.
4. TIH with 3-7/8" bit, bit sub, and watermelon mill on 2-3/8" tubing and round trip to PBTD, cleaning out with air/mist. **NOTE: When using air/mist, mist rate must not be less than 12 bph.** Speak with Operations Engineer, and if necessary, determine the best way to remove scale from the casing and perforations.
5. TIH with one joint of 2-3/8" tubing with expendable check, F-nipple (one joint off bottom), then 1/2 of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing. Replace any bad joints. CO to PBTD with air/mist. Report water production rate to Operations Engineer.
6. PU above the top Dakota perforation at **7884'** and flow the well naturally, making short trips for clean-up when necessary.
7. Land tubing at **8015'**. Obtain pitot gauge from casing and report this gauge. Broach the upper 1/2 of the production tubing. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. If well will not flow on its own, make swab run to SN. RD and MOL. Return well to production.

Recommended: *Tom Loveland* 10/19/98 Approved: *Bruce W. Bony* 10-27-98
Operations Engineer Drilling Superintendent

Operations Engineer: L. Tom Loveland

Office 326-9771
Pager 324-2568
Home 564-4418