UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



99 MAY 10 PM 2: 25

Sundry Noti	ces and Reports on Wells	070 FIRE . C. ON, NA
1. Type of Well GAS	DECER MAY 1	(10,110
2. Name of Operator BURLINGTON RESOURCES OIL 8	ON DIE	Collins San Juan Unit San Juan Unit
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M 1700'FNL, 1650'FEL, Sec.16, T-28-N, R-5-W, NMPM		8. Well Name & Number San Juan 28-5 U #84 9. API Well No. 30-039-20360 10. Field and Pool Basin Dakota
	G	11. County and State Rio Arriba County, No.
12. CHECK APPROPRIATE BOX TO IND Type of Submission _X Notice of Intent Subsequent Report Final Abandonment	Type of Action Abandonment Recompletion Plugging Back Casing Repair	n Change of Plans New Construction Non-Routine Fracturing Water Shut off Conversion to Injection
Describe Proposed or Compl It is intended to repair t procedure.	-	well according to the attached
14. I hereby certify that the Signed Manuel	foregoing is true and cor	
(This space for Federal or State APPROVED BY Spincer CONDITION OF APPROVAL, if any:	e Office use) Tit [™] @ ²³³ & & Franks May	MAY 1 0 1000

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

San Juan 28-5 Unit #84 Basin Dakota

Unit G, Sec. 16, T-28-N, R-5-W Latitude / Longitude: 36° 39.82176' / 107° 21.64122'

Recommended Tubing Repair Procedure 4/20/99

Project Justification: The San Juan 28-5 Unit #84 was completed in 1971 as a Dakota producer, and has not been pulled since that time. An uncharacteristically shallow decline was the first indication that a downhole restriction may have been limiting gas production. In October 1993, an attempt to recover the bottom-hole bumper spring proved unsuccessful due to scale buildup. Acid was pumped down the tubing shortly after, and another attempt to pull the spring was made in December 1998. The second attempt also proved unsuccessful due to sandfill discovered by an impression block. A new bottom-hole bumper spring was set above the first, and the well again began producing with a plunger-lift system. The bumper spring restriction, in conjunction with the well's tendency to precipitate scale, will continue to limit production un ess removed.

NOTE: ALL DEPTHS ARE MEASURED FROM KB. KB to GL was 9'.

- Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Prior to 1. moving in rig, make one-call and then verify rig anchors and dig pit.
- MIRU workover rig. NU relief line and blow well down (kill with 2% KCL water only if necessary). 2. ND WH and NU BOP. Test and record operation of BOP rams. Replace any WH valves that do not operate properly. Test secondary seal and install or replace if necessary. Note: Donut and WH will need to be changed for 2-3/8" tubing.
- NOTE: This well produces with a plunger-lift system. Dakota, 1-1/2", 2.9#, MCW-55 tubing set 3. at 7911' (246 jts). Broach tubing and set tubing plug in tubing at 7800'. Release donut, pick up additional joints of tubing and tag bottom, recording the depth. PBTD should be at +/- 7961. TCOH and LO 1-1/2" tubing. Visually inspect tubing for corrosion, and report the number of bad joints to the Operations Engineer. Check tubing for scale and notify Operations Engineer and Drilling Superintendent if it is present.
- PU 3-7/8" bit, bit sub, and waterme on mill on 2-3/8" tubing and round trip to PBTD, cleaning out 4 with air/mist. NOTE: When using air/mist, mist rate must not be less than 12 bph. Speak with Operations Engineer and Drilling Superintendent, and if necessary, determine the best way to remove scale from the casing and perforations.
- TIH with one 4' pup joint of 2-3/8" tubing with expendable check, F-nipple (above pup joint), then $\frac{1}{2}$ 5. of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing. Replace any bad joints. CO to PBTD with air/mist.
- PU above the top Dakota perforation at 7808' and flow the well naturally, making short trips for 6. clean-up when necessary.
- Land tubing at 7911'. Obtain pitot gauge from casing and report tills gauge. Ereach the upper $\frac{1}{2}$ 7. of the production tubing. ND BOP and NU WH. Fump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped cff. If well will not flow on its own, make swab run to SN. RD and MOL. Return well to production.

perations Engineer

Approvec: Druce (). Sou

Office

Pager

Operations Engineer:

L. Torn Loveland

326-9771 324-2568

\\StreetTalk\Shared@OPRprd@FAR\tlove an\Area 8 Wells\Tubing Repair\28-5\84\Treppro.doc