5 Form \$160-5 (June 1990)

representations as to any matter within its jurisdiction.

# UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

RECEIVED

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

Do not use this form for proposals	ES AND REPORTS ON WELLS  to drill or to deepen or reentry to significant reservoir.	Lease Designation and Serial No.     NM-14915     6. If Indian, Allottee or Tribe Name		
	670 Pringing TO: I, No.	7. If Unit or CA, Agreement Designation		
1. Type of Well  Oil Gas Well Other				
Well Well Other  2. Name of Operator	Attention:	8. Well Name and No.		
Amoco Production Company	Valencia Canyon Unit 24			
3. Address and Telephone No.	3003921592			
P.O. Box 800, Denver, Colorado 803	10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey	Choza Mesa Pictured Cliffs			
1050' FNL 1130'FW	11. County or Parish, State			
	Sec. 15 T 28N R 4W Unit D	Rio Arriba New Mexico		
12. CHECK APPROPRIATE	BOX(s) TO INDICATE NATURE OF NOTICE, F			
TYPE OF SUBMISSION	TYPE OF ACTION	EFORT, OR OTHER DATA		
	THE ST ACTION			
Notice of Intent	Abandonment	Change of Plane		
	Recompletion Plugging Back	New Construction		
Subsequent Report	Casing Repair	Non-Routine Fracturing  Water Shut-Off		
Final Abandonment Notice	Altering Casing	Conversion to Injection		
- The resulting House	Other	Dispose Water		
	Recompletion	ort results of multiple completion on Well Completion or on Report and Log form. )		
Committee and measured and most yearness	state all pertinent details, and give pertinent dates, including estimated date of starting depths for all markers and zones pertinent to this work.]*  ests permission to perform the casing repair work per the			
		The second secon		
		DEGEEVED N jun 1 2 1995		
		OIL COM. DIV. Det. 3		
14.1 hereby certify that the foregoing is true and correct				
Signed Patty Haefele	Title Staff Assist	ant Date 05-18-1995		
(This space for Federal or State office use)				
Approved by Conditions of approval, if any:	Title	A P P P O V F D		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any Michigans, or Michigans at the same matter within the inviscious, or Michigans at the same matter within the inviscious of the United States and Michigans at the same matter within the inviscious of the United States and Michigans at the same matter within the inviscious of the United States and Michigans at the same matter within the inviscious of the United States and Michigans at the same matter within the inviscious of the United States and Michigans at the same matter within the inviscious of the United States and Michigans at the same matter within the inviscious of the United States and Michigans at the same matter within the inviscious of the United States and Michigans at the same matter within the inviscious of the United States and Michigans at the same matter within the inviscious of the United States and Michigans at the same matter within the invited states and the same matter within the invited states and the same matter within the invited states at the same matter within the same matter within

## SJOET Well Work Procedure

Wellname:

**VCU 24** 

Version:

#1

Date:

May 15, 1995

Budget:

DRA, Repair Well

Workover Type:

Casing Repair

#### Objectives:

This well had a casing leak and repair 5/12/93, current conditions suggest another leak.

CBL will be run to locate cement tops.

Casing integrity will be checked and repaired if necessary.

Tubing will be raised to 4136'.

Pertinent Information:

Location:

1050' FNL, 1130' FWL, D15-28N-4W

Horizon:

PC

County: State:

Rio Arriba New Mexico

API#: Engr:

30-039-21592

Lease:

Federal # NM-14915

Phone:

Mark Rothenberg W--(303)830-5612

Well Flac:

H--(303)696-7309

**Economic Information:** 

APC WI:

100%

PC Prod. Before Repair:

0 MCFD

**Estimated Cost:** 

\$25,000

PC Anticipated Prod.:

50 MCFD

Pavout:

21 months

Max Cost -12 Mo. P.O.

\$14,460

PV15:

Max Cost PV15:

\$M \$M

\*Note:

This work has to be done for regulation compliance. All charges will go against the

DRA account except those done to bring the well back on line.

Formation Tops: (Estimated formation tops)

Nacimento:

Oio Alamo: 3500 Menefee:

Kirtland Shale:

CSG

4043

Point Lookout:

Fruitland:

3734

Mancos Shale:

Pictured Cliffs:

Gallup:

Lewis Shale:

Greenhorn:

Chacra:

Graneros:

Cliffhouse:

Dakota: Morrison:

**Bradenhead Test Information:** 

BH

Test Date:

Tubing:

Casing:

**CSG** 

INT

BH:

Time 5 min

10 min

15 min

Comments:

BH not tested since repair in May, 1993.

Wellname: VCU 24

Page 2 5/17/95

### Suggested Procedures:

- Contact Federal or State agency prior to starting repair work and forest services (Tim Tinsfield 505-632-2956).
- 2. Catch gas and/or water sample off of bradenhead and casing, and have analyzed.
- 3. Install and/or test anchors.
- 4. MIRUSU. Check and record tubing, casing and bradenhead pressures.
- 5. Blow well down, kill well if necessary with 2% KCL.
- 6. Nipple down well head, nipple up and pressure test BOP's.
- 7. Trip in the hole and tag PBTD, check for fill, trip and tally out of hole with tubing checking condition of tubing.
- 8. Trip in the hole with RBP and PKR. Set RBP 50-100 ft. above perforations. Trip out of hole one joint and set PKR and pressure test RBP to 1500 psi. Release PKR, spot sand on RBP and pressure test csg to 1000 psi. If no leak is found, trip out of hole with RBP and PKR and skip to step 16.
- 9. Trip out of hole isolating leak in casing. Trip out of hole with PKR.
- 10. Run CBL from 3800' to surface under 1000 psi and fax results to Denver attn: Mark Rothenberg (303-830-9262)..
- 11. Based on the location of the leak and the results of the CBL, perforate casing if necessary with 2 squeeze holes and circulate dye if possible to determine cement volume. Depending on the depth of the hole and circulating pressure, a PKR or a cement retainer may be needed.
- 12. Mix and pump sufficient cement (class B or equivalent with two hour setting time) to circulate to surface, if circulation to surface is possible. Shut bradenhead valve and attempt to obtain a squeeze pressure and WOC.
- 13. Trip out of hole. Trip in the hole with bit and scraper and drill out cement and pressure test casing. Re-squeeze leaks if casing fails pressure test.
- 14. If cement is not circulated to the surface, it may be necessary to run another CBL (and/or temperature survey 8-10 hours after cementing) and repeat steps 11 thru 13.
- 15. Trip in the hole with retrieving head for RBP, circulate sand off of RBP and trip out of hole with plug.
- 16. Trip in hole with a sawtooth collar and/or bailer and clean out to PBTD and trip out of hole.
- 17. Trip in the hole with the production string (1/2 mule shoe on bottom and a seating nipple one joint off bottom), removing joints to land tubing at 4136'. Nipple down BOP's, nipple up well head.
- 18. Swab well in and put well on production.
- 19. Rig down move off service unit.

If problems are encountered, please contact:

MARK ROTHENBERG

(W) (303) 830-5612 (H) (303) 696-7309

WI: 1.0 HET = 27.5

# Amoco Production Company

Sheet No Cf

ENGINEERING CHART

	SUBJECT_	VCU	24-PC	API:	30039	21592	Federat	العلامة	Daie 5/15/45
k . 44.	<u>D</u>	15-28N-4	IW, Plotriba	105	OFNL	, 1130 F	WL NN	1-14915	By MDR
Depti-	**************************************			* * * * * * * * * * * * * * * * * * *		i i Teressa	TO EAT 2	2 111 4 94	factors and a second se
۔ ح <sub>ک</sub> ا	_ ESTI	IMATED TORS				1//	X Bayo	appel" her he its	318') 250 SK CMT CI
مود	OA	3500'			7				to
375	- FT				4	1 //		5/8" 24#	K-55 U6@318
SUD	PC	4043	]				.1		100 Ca 6 218
ت د		The same of the sa					\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		er en la propiet de la company de la comp
750						, . <u>-</u>			error en la companya de la companya
875			•	)					
1000 -	<del></del>					****			Confidence and the confidence of the confidence
1725				(					The second of th
وردا	=						/	7 7/8" hale	to 4400 -TD)
1375									IX CHIND CANT TO SUFFACE)
1500		·				-   )			The state of the s
125								The second secon	PRIOR WORK
1750					.	(	· 1	5/12/93	
1875							/		CSC LEAK @ 292-39
7010 —				(					Br indirted 020 Itoly
، جراء						17			CE, HELD 1500
220				<u> </u>				E PROMONENT OF THE R	the many of the section of the secti
2375						-   - (	* eng		the term of the second
~5500 ·	_	* ********				· ' '	• • • • • • • • • • • • • • • • • • • •		to the <del>c</del> onstruction of the construction
A).D	<b>-</b>			\.		. )			
			••				* * * *	-9-	en de la companya de
سية جاد سية جاد				4		1	•		The second of th
300 <b>-</b>	· · · · · · · · · · · · · · · · · ·								en e
JI 45 -	_			<i>i</i>			****		* *
3×50 ·	_			`/					· · · · · · · · · · · · · · · · · · ·
- صن 3 - صن 3		· · · · · ·	25700			1			
	OJO ALA	-wo				12			· · · · · · · · · · · · · · · · · · ·
م روهنور م			3734				٠		
J770 -	· ·	· · · · · · · · · · · · · · · · · · ·	Par-15	- M			\ /		*** *** *** *** **** *****************
7875 -	FRUTLAN	Δ	4047-53				•		
40CO —	PICTURES O	4043	4056-74 4091-4124 4128-36				•		
		LLIFFS	(187,000 ± sand	,			•		
4215 -	•		4215-82	(			<i>238</i> ″ т	-55 . KAI A	lule shoe @ 4299'
- جرد <sup>ر با</sup> - ردر <sup>ر با</sup>			السعر لل 13,000 م	1 4	•	7	4/2", 10,5	ر ۱۳۰۸ د - دی ۲-53 را	6 e 4400'
				•	-	_	-	· <del>-</del> -	- , , <del>-</del> -

Engr: zmdr16