

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

078092

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Douthit "C" Federal

9. WELL NO.

2

10. FIELD AND FOOT, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLE. AND
SURVEY OR AREA

Sec 27-T27N-R11W

12. COUNTY OR PARISH 13. STATE

San Juan

NM

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
Gulf Oil Corporation

3. ADDRESS OF OPERATOR
P. O. Box 670, Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1850' FSL & 790' FWL

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6350' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ FULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) Repair Casing Leak ☒


SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DES. RICE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

POH with tubing string. Set CIBP at 6100', packer directly above CIBP. Move packer up hole until leak is found, using 500# as a test pressure. Reset packer 300' above leak. Establish injection rate with 2% KCL fresh water. Squeeze leak with 200 sacks Class "B" cement + 2% CaCl₂. Test casing above cement to 500#, squeeze any leaks if necessary. Drill out cement to bottom leak. Test squeeze to 500#. Drill out CIBP. Clean out hole to bottom. GIH with producing equipment. Swab & return well to production.



Stephen M. ...
for

18. I hereby certify that the foregoing is true and correct

SIGNED RD Pitzer TITLE Area Engineer

DATE 10-22-80

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE Area Engineer
10-22-80

DATE