Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED				
Budget Bure	eau No.	1004-0135		
Expires:	March	31, 1993		

5. Lease Designation and Serial No

6. If Indian, Allottee or Tribe Name

Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Dispose Water

I-149-IND-8464

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals

Marraia Allottod

		_ Navajo Allotteu
SUBMIT II	N TRIPLICATE, Discussion Fail	7. If Unit or CA. Agreement Designation
1. Type of Well Oil A Gas Other 2. Name of Operator Texaco Exploration & Production Inc. 3. Address and Telephone No. 3300 N. Butler, Farmington N.M. 8	37401 (505)325-4397 JAN21'1984	Nellie Platero #3 9. API Well No. 30-045-06637 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Described 1650' FSL & 1650' FWL NE/4, SW/4, Sec. 11, T27N, R9W	ription)	Basin Fruitland Coal 11. County or Parish. State San Juan, NM
12 CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Report	Abandonment Recompletion Plugging Back	Change of Plans New Construction Non-Routine Fracturing
	Casing Penair	Water Shut-Off

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally critled. give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

X Casing Repair

Other

Altering Casing

Texaco Exploration & Production Inc. plans to perform the following work to the subject well:

1. MIRUSU. NDWH. NUBOP.

Final Abandonment Notice

- 2. POOH with 2-3/8" tubing.
- 3. RIH with RBP and PKR. Hunt hole. Identify top and bottom of leak. Spot sand on top of RBP. POOH with TBG and PKR.

NOTE: Casing leak identified at 1001'-1019' on 1//08/94. Rate 2 BPM at 200 psi.

- 4. RIH with 5-1/2" CMT RETR on 2-3/8" tbg. Set CMT RETR 100' (901') above top of casing leak.
- 5. Pump 30 Bbls linear gel. Circulate gel to surface. Pump 300 sacks class "G" cement with LFL additive. After cement circulates to surface close casing valve and squeeze.
- 6. Sting out of CMT RETR, pull up 30' and reverse out excess cement.
- 7. RIH with 4-3/4" bit, drill out cement to top of RBP, circulate clean, and pressure test casing to 1000 psi. If casing does not pressure test, evaluate for re-squeeze.
- 8. RIH with retrieving head and POOH with RBP. RIH with 2-3/8" production tubing open end at 1992'. Swab fluid to unload wellbore.
- 9. NDBOP. NUWH. Return well to production.

14. I hereby certify that the foregoing is true and correct Signed	Title Area Manager	Date 1/10/94
(This space for Federal or State office use)		APPROVED
Approved by	Title	JAN 3 1994
Title 18 U.S.C. Section 1001, makes it a crime for any personal section 1001 and the section 1001 and the section 1001 are section 1001.	on knowingly and willfully to make to any department or	agency of the United States any false. Fictitious or traudulent statemen
or representations as to any matter within its jurisdiction.	*See Instruction on Reverse Side	
m	į	TRB