# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK

	TYPE OF WORK PLUG BACK TYPE OF WELL	5. LEASE NUMBER SF-077874
1.0.	GAS WELL	6. IF INDIAN, ALL. OR TRIBE NAME
2.	OPERATOR SOUTHLAND ROYALTY COMPANY	7. UNIT AGREEMENT NAME
3.	ADDRESS & PHONE NO. OF OPERATOR P.O. BOX 4289 FARMINGTON, NM 87499 (505) 326-9700	8. FARM OR LEASE NAME HANKS 9. WELL NO. #5
4.	LOCATION OF WELL 1450' FSL, 790' FWL	10. FIELD, POOL, OR WILDCAT BASIN FRUITLAND COAL 11. SEC. T. R. M OR BLK. SEC. 07, T26N, R09W
14.	DISTANCE IN MILES FROM NEAREST TOWN	12. COUNTY 13. STATE SAN JUAN NM
15.	DISTANCE FROM 16. ACRES IN LE PROPOSED LOCATION TO NEAREST PROPERTY OR LEASE LINE.	ASE 17. ACRES ASSIGNED TO WELL 321.58
18.	DISTANCE FROM 19. PROPOSED DE PROPOSED LOCATION TO NEAREST WELL DR. COMPL., OR APPLIED FOR ON THIS LEASE.	PTH 20. ROTARY OR CABLE TOOLS
21.	6186 DF	22. APPROX. DATE WORK WILL START
23.	PROPOSED CASING AND CE	MENTING PROGRAM
24.	*SEE OPERATIONS HEAD AUTHORIZED BY: Segulatory Affairs	OCT 5 1990 DATE
PERMI	T NO APPROVAL DATE	DIST. 3
APPRO	VED BY TITLE	DATE
NOTE:	THIS FORMAT IS ISSUED IN LIEU OF US BLM (NO ADDITIONAL DIRT WORK WILL BE REQUIRE	FORM 3160-3.  APPROVED  OCT 0 2 1990  FOR AREA MANAGER

State Lease - 4 copies
For Lease - 3 copies

## State of New Mexico ... Energy, Minerals and Natural Resources Department ...

Port C-1822

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

### OIL CONSERVATION DIVISION P.O. Box 2088

DISTRICT II
P.O. Drawer DD, Artena, NM 88210


Santa Fe, New Mexico 87504-2088

DISTRICT III
1000 Rio Brance Rd., Aziec, NM 87410

### WELL LOCATION AND ACREAGE DEDICATION PLAT

Operator	Al Oli	tences must be	from the outer boundaries	of the section	
Southland			L4103-		Well No.
Unit Letter Section	Royalty Compar	ıy		F-077874)	5
L	7 27 No.	th	9 West	Count	San Juan
Actual Footings Leastion of	Wed:			NMOM	San Juan
1450 feet f	South	Line and	790	_	Vest
6176'	Fruitland Co		Pool	foat from the	Deline America
1. Outlins the ac	rate dedicated to the subject we		Basin		321.58
2 17		A COURSE PARC	il or hadron marks on the p	ist below.	Acres
بر رحد	no lease is dedicated to the well, (	i kas daan endise	leasily the connectaip thereo	(both as to working interest	t and royalty),~.
7 11 2020 (1982) (1	to locate of different expension in		rell, have the interest of all (		•
Yes-				warm sees contributed by	COMPANIES NO.
If the same is fact.	the time owners and owners described	and "hee" type	of constitutions— sensity been constituted((		
this form if moon No allowable will	be accepted to the wed total all i			100 100 mile of .	
or testi a non-sta	dead wall, distincting state inter-	Mariana ingve beni S. into bean arrow	econotidated (by commune wed by the Division.	IZZEGO, URBITZADOR, FORCES (	coling, or otherwise.
			- DIVIEW		
Not re-surve	eyed prepared		1	OPE	CATOR CERTIFICATION
from a plat	by Charles		1	Am	reby carryly that the informati
J. Finklea o	lated 1-4-52.	-	!	best of my	novem in the and complete to t restricted and balls.
	i	10) ie	CEIVER	Mari	Malhued
	i l		PANELL ST	Signature 7	y Bradfield
	i I	U(	OT 5 1890	Prison New	y Bradfield
			1 2 MAII		latory Affairs
		OIL	CON. DIV.	Position -	
			DIST. 1	Sout	hland Royalty Co
				Company	-20-9,
			i i	Date :	20 -9)
		<b></b> .	1	1 1	
			umhumm.	CITE V	TVOR OFFI
j	/1			3000	EYOR CERTIFICATIONS
İ	1		<u> </u>	I haveby car	my that-the-well-leasting-show
1			ł		was-planted-from-field-manner
ļ			i		and their thereasure in the same
790'			i	Lating 18	As - Dest-of -say-insuladgement
			İ	Day 6	-19-90
					17.5
			[	Signatura	
8				Profession	HE TO SEL
5					* **
Υİ			ļ		(6857)
			1		6857
71111111111111111			i	Commen	
		44444444	9999999999	Neal	TI LIME
JJ 60 ÷ 990 ± 1330	3 1689 × 1989=2320 = 2640	2000 :-	1500 - cos		E PRINCE

# HANKS #5 WELLBORE DIAGRAMS




#### RECOMPLETION PROCEDURE Hanks #5

- 1. Prepare location for workover. Install or replace anchors as necessary.
- MOL with workover rig, hold safety meeting, install safety signs and proper fire equipment at strategic points. Comply with all BLM, NMOCD, and MOI regulations.
- 3. Rig up blow lines, record tubing and casing pressures and blow well down. NU 6" 3000 psi BOP and test. Load hole with water.
- 4. TOOH with 1" tubing.
- 5. PU 5 1/2" casing scraper and TIH with 2 3/8" 4.7# J-55 EUE tubing. CO to 2090'.
- 6. TOOH. RU wireline unit and set a 5 1/2" CIBP at 2090'. Pressure test casing to 2500 psi for 15 minutes. Run logs.
- 7. Perforate coal. Perforations to be picked from log.
- 8. TIH with 2 3/8" tubing and swab wellbore dry. Check well for gas flow. Evaluate well overnight. Check well for buildup pressure and gas flow. Evaluate for fracture stimulation. A fracture stimulation procedure will be provided if required. TIH with 2-3/8" tubing and clean out to CIBP.
- 9. When well is clean, land 2-3/8" tubing with a common pump seating nipple one joint off bottom. Land tubing. Swab well in. Record final 30, 45 and 60 minute gauges on morning report. ND BOP. NU tree. RD and release rig.
- 10. Shut well in for pressure build up. Obtain gas and water sample for analysis.

Approve:				
	R.	F.	Headrick	

SHL:RCT

## WORKOVER / RECOMPLETION B.O.P. SCHEMATIC



MINIMUM: 6" 2000 PSI DOUBLE GATE B.O.P.

MAXIMUM ANTICIPATED SHUT-IN WELLHEAD

PRESSURE IS LESS THAN 2000 PSI