Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR RUBEAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

BUREAU	OF LAND MANAGEMENT RECEIV	
Do not use this form for propo	FICES AND REPORTS ON WELLS Figure 1 is a sale to drill or to deepen or reentry to a different reservoi	SF-078019
	970 F. C	7. If Unit or CA, Agreement Designation
1. Type of Well Oil Well Well Other		8. Well Name and No.  F. H. Pinkin #8X
2. Name of Operator	Attention:	E. H. Pipkin #8X
Amoco Production Company	Pat Archuleta	
3. Address and Telephone No.	80201 (303) 830-5217	3004506788
P.O. Box 800, Denver, Colorado	80201	
4. Location of Well (Footage, Sec., T., R., M., or S	Survey Description)	Basin Dakota
1070'FSL 1610FWL	Sec. 01 T 27N R 11W Unit N	11. County or Parish, State
1070132 10101442	Jec. 01 1 27N N 11W Only	San Juan New Mexico
12. CHECK APPROPRIA	ATE BOX(s) TO INDICATE NATURE OF NO	TICE , REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF	ACTION
Notice of Intent  Subsequent Report  Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other Repair	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut-Off  Conversion to Injection  Dispose Water  (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Amoco Production Company requests permission to perform a bradenhead repair on this well per attached procrdures.



Signed La Schulta	Title	Clerk A D D Dato V 5-10-1996
his space for Federal or State office use)		
Approved by Conditions of approval, if any:	Title	JUN 1:1 1996
tle 18 U.S.C. Section 1001, makes it a crime for any person knowingly and presentations as to any matter within its jurisdiction.	willfully to make to any deputing	Dy of the United Stateschy fall ANSFAICT II MANAGER to or

E.H. Pipkin #8X Orig. Comp. 1/61

**Elevations:** GL = 5762', KB = 5773'

TD = 6269', PBTD = 6235'

## Notice of Intent to Perform Bradenhead Repair

Brief description of work: The EH Pipkin #8X was initially completed 1/61. In 1/64 a casing leak was found and repairs attempted via cement squeeze techniques. A casing inspection log was ran during the procedure. The historic records are unclear as to whether the casing leak was repaired. However, a retrievable packer was set above the DK. The annular space was filled with a lightly gelled mud for a packer fluid. Current pressure measurements show 0 psig on the casing. It's possible that the casing leak was repaired and that the packer and packer fluid were installed on a preemptive basis. The purpose of this work is repair an identified bradenhead problem. However, uncertainty exists regarding the productivity of the DK and the condition of the casing. Prior to repairing the bradenhead, the objective is to isolate and obtain a good flow test of the DK to determine its productivity. If acceptable, the easing integrity will then be tested. The decision to repair the casing or not will depend upon the pressure test results and any pump in data gathered if a leak is found. The bradenhead will then be repaired.

The uncertainty for the DK production stems from the fact that the historic production data from this well show that it has never exceed about 70 MCFD. The historic data only goes back through 1970, post casing leak. Analysis of logs, reserves, and offsets indicate that this well should be capable of production in excess of 100 MCFD. This is supported by the high SITPs that have been measured on this well (~800 psig).

If we are unable to achieve 50 MCFD or greater from this well then we will proceed with PxA procedures, pending regulatory approval. Also, if we can achieve the target production rate but are unable to repair the easing leak we will seek regulatory approval to install a retrievable packer to isolate the leak and load the annulus with inhibited packer fluid.

Given the uncertainty in this repair, close communication and coordination will be required with the regulatory agencies.

E.H. Pipkin #8X Orig. Comp. 1/61 Elevations: GL = 5762', KB = 5773' TD = 6269', PBTD = 6235'

Page 2 of 4

- 1. Contact Federal or State agency prior to starting repair work.
- 2. Catch gas and/or water sample off of bradenhead and casing, and have analyzed.
- 3. Install and/or test anchors on location.
- 4. MIRUSU. Check and record tubing, casing and bradenhead pressures.
- 5. Set retrievable plug in tubing immediately above packer. Blow down tubing.
- 6. ND wellhead. NU and pressure test BOP's.
- 7. RU HES. Perforate tubing above retrievable plug. Circulate out packer fluid. Contain packer fluid and dispose of per environmental standards.
- 8. Release packer and TOOH with tubing and retrievable packer. Note that packer has been in the hole since 1/64.
- 9. TIH w/ tubing. Tag for fill. Clean out if found across perforated interval. TOOH w/ tubing. TIH with tubing x retrievable packer. Set packer above DK and test x swab DK. Report results to Denver for decision on PxA versus return to production. Note: May attempt to reperforate DK if any evidence of scale is found. TOOH w/ tbg x pkr.
- 10. TIH with RBP and packer. Set RBP 50-100 ft. above perforations. TOH one joint and set packer. Pressure test RBP to 500 psi.
- 11. Pressure test casing above packer—Isolate leak, if any, by moving packer up the hole and repeating pressure test.
- 12. Establish injection rate into leak, if found, and attempt to circulate to surface.
- 13. Release packer, spot sand on RBP and TOH with packer.
- 14. Run CBL and CCL to determine cement top. Note: Highest cement top calculated at 940'.
- 15. Perforate casing above cement top, if necessary, with 4 JSPF and circulate dye to determine cement volume.
- 16. Depending on depth of hole and circulating pressure, a packer or cement retainer may be needed.
- 17. Mix and pump sufficient cement (Class B or equivalent, with a setting time of 2 hours) to circulate to surface. Shut bradenhead valve and attempt to walk squeeze to obtain a 500 psi squeeze pressure. WOC.
- 18. TIH with bit and scraper and drill out cement. Pressure test casing to 500 psi. TOH with bit and scraper.
- 19. TIH with retrieving head for RBP. Circulate sand off of RBP and TOH with RBP.
- 20. TIH with production string (1/2 mule shoe on bottom and seating nipple one joint off bottom) and land tubing at 6130-40'. NDBOP. NU wellhead.

E.H. Pipkin #8X Orig. Comp. 1/61 Elevations: GL = 5762', KB = 5773' TD = 6269', PBTD = 6235' Page 3 of 4

- 21. Swab well in and put on production.
- 22. RDMOSU.
- 23. Take final bradenhead pressures and log date/pressures in CRWS.

If problems are encountered, please contact:

Steve Webb

(W) (303) 830-4206 (H) (303) 488-9824

Brief description of work: The EH Pipkin #8X was initially completed 1/61. In 1/64 a casing leak was found and repairs attempted via cement squeeze techniques. A casing inspection log was ran during the procedure. The historic records are unclear as to whether the easing leak was repaired. However, a retrievable packer was set above the DK. The annular space was filled with a lightly gelled mud for a packer fluid. Current pressure measurements show 0 psig on the easing. It's possible that the easing leak was repaired and that the packer and packer fluid were installed on a preemptive basis. The purpose of this work is repair an identified bradenhead problem. However, uncertainty exists regarding the productivity of the DK and the condition of the easing. Prior to repairing the bradenhead, the objective is to isolate and obtain a good flow test of the DK to determine its productivity. If acceptable, the easing integrity will then be tested. The decision to repair the easing or not will depend upon the pressure test results and any pump in data gathered if a leak is found. The bradenhead will then be repaired.

The uncertainty for the DK production stems from the fact that the historic production data from this well show that it has never exceed about 70 MCFD. The historic data only goes back through 1970, post easing leak. Analysis of logs, reserves, and offsets indicate that this well should be capable of production in excess of 100 MCFD. This is supported by the high STTPs that have been measured on this well (~800 psig).

If we are unable to achieve 50 MCFD or greater from this well then we will proceed with PxA procedures, pending regulatory approval. Also, if we can achieve the target production rate but are unable to repair the easing leak we will seek regulatory approval to install a retrievable packer to isolate the leak and load the annulus with inhibited packer fluid.

Given the uncertainty in this repair, close communication and coordination will be required with the regulatory agencies.

	Amoco Production Company	Sheet No Of File
	ENGINEERING CHART	Appn
SUBJECT EHPIPKIN + B	X 1070 FSLY 1610 FORL	Date 4/18/96
UNITH, Sec. OL	TO MERILW	By JW
		#18 2000 Volu
RDB- 5773'-		SEC CS C PROB >PXI
Cr. 21109, -		18x 5000 47/61
		# 5/12/6/ @
		1301 Mad
	S MALE AS BOOK IN	20 FLOD
	52 462117 C	Bridge 1
		C2V 293
	B1 D10 12135	1107 651
	(CNIC TOC 940	)')
	1/4	
	Notes in CSS	
Ye.	3353-31104'	
	0×	<b>\</b>
Septe of		TBG: 23/8" 4.7# 75A6125
3º mind		BITM- X-PID COLLAR
1		Same Karing COCCAR
	BAYER MODEL R	
LEW HOW BUT ( PISO- DC ) B		
SOND ((121-12), 의 * HOM 기		
TRA DEMONE	4'5"9.54 CON 63	′
A 18 WA SOLAD	25.27 (*53.2) CML CM 512.24	
	DDI \W CM JIAT	SX NF AT
	(CALC TOC 4NS	o' \
FPI: 3004506788		4716
12E - 3F - 078019	٦/ <sub>٦٩</sub>	712
PURCHASER - WES	1/83	
WELL FLAC 924379	3/23	195
GHETER # 30597	85/8.	700
		,00