Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

BOREAU OF LAND MANAGEMENT	
THE PERSON OF TH	5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS	SF-077941
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.	6. If Indian, Allottee or Tribe Name
Use "APPLICATION FOR PERMIT - " for such proposals	
	7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gas Well Other	8, Well Name and No.
	C. A. McAdams C #2
2. Name of Operator AMOCO PRODUCTION COMPANY ARCHITECTURE Pat Architecta	9. API Well No.
3. Address and Telephone No.	3004506845
P.O. BOX 800 DENVER, COLORADO 80201 303-830-5217	10. Field and Pool, or Exploratory Area Basin Dakota
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	11. County or Parish, State
2090' FSL 1680' FWL Sec. 5 T 27N R 10W UNIT K	SAN JUAN NEW MEXICO
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE	, REPORT, OR OTHER DATA
TYPE OF ACTI	
TYPE OF SUBMISSION	
Abandonment	Change of Plans
Notice of Intent	New Construction Non-Routine Fracturing
Subsequent Report Plugging Back Casing Repair	Water Shut-Off
Altering Casing	Conversion to Injection
Final Abandonment Notice Other Repair	
Reco 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of a	rmpletion Report and Log form.)
Verbal approval from Wayne Townsend to Rudy Candelaria on 8/23/96, also file NOi a	nd Subsequent at the same time.
DEGETAL 17 1837	
OIL COM. [Dist. 3	
14. I hereby certify that the foregoing is true and carrect Signed La Cachella Title Staff in	Assistant Date 06-10-1997
(This space for Federal or State office use)	JL 5 199
Approved by Title	J410
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the Uni representations as to any matter within its jurisdiction.	ted States any false, ficticious, or fraudulent statements or

C.A. McAdams C #2 Orig. Comp. 5/64 TD= 6420', PBTD = 6383'

Elevations: GL = 5886', KB = 5900'

Page 2 of 2

- 1. Contact BLM prior to starting repair work.
- 2. Catch gas sample off of braden head and casing, have analyzed.
- 3. Test anchors, install if necessary. MISURU.
- 4. Blow down and kill well if absolutely necessary kill with 2% KCL
- 5. Isolate Dakota with Wireline BP.
- 6. TIH with RBP X Packer. Hunt for leak. (Suspected in the Mesa Verde) Note: Two leaks found. One leak in Lewis at ~2000' and one leak found in lower MV at ~4160'. Found leaks during routine tubing optimization work.
- 7. Isolate each leak. Dump sand on top of RBP.
- 8. Spot Cement plug across each failure. Pressure up cement.
- 9. Pressure test each cement plug prior to drill out. Drill out cement and pressure test casing to 500 psi. Clean out to RBP. Circulate sand off of RBP and retrieve.
- Swab/flow test DK to determine whether production has been impaired. Notify engineer of results.
- 11. Reland production tubing at 6320-30' KB.
- 12. Swab/flow to clean up. Return well to production.

Note: Well is capable of production in excess of 150 MCFD. Recent test data and pressure data suggest that this well has a tubing leak and is therefore unable to unload liquids. This well is only producing at 50 MCFD due to its inability to unload liquids. Recent attempts to install plunger have been unsuccessful as plunger would not cycle despite having broached tubing. Casing pressure bleeds down slightly as tubing is vented. Data suggests that a tubing leak is present. Have a copy of wireline report in Farmington.

SEL is \$25,000 so no prior approvals (permitting or partners) are required. Well not entered in OARS as planned for well servicing budget. Please notify engineer if situation indicates that costs should be charged to repair well budget so OARS can be built.

NOTE: Found casing leak during tubing optmization job. Isolated two casing leaks (one in the Lewis at 2000' and one in the MV at 4160'). Unable to achieve a pump in rate but pressure would bleed off slowly. Leak was initially indicated by the presence of scale on the outside of the tubing. The presence of scale was limited to a very small area which makes us believe that we have limited corrosion. We made the decision to repair the leak by attempt to cement squeeze as outlined in the procedure above. We will test the DK after we complete the casing repair to determine if it needs reperforated or a small acid job to clean up/bypass scale.

	Amoco Production Company		Sheet No Of File
ENGINEERING CHART		Appn	
SUBJECT C. A. McADA	MZ (413 3000, E	CTX 1080, EDT	Date _ 4 / 11 /9(
UNITK, SEC	5, TOTO-ROW		8y_,5kw
			SPUD 4/10/64
KB 5900'			IP \$5/64
GL-5886'			@ 5550 MCFD
		3470 Car	asusk Bul
DX PERFS : DSPF		D1 @ 4544' CMT W(9505X) TBG: 03	Дшктееютн В/в" Ц-74 ТSA 6330'
# 30/40 (230-30') # SM# 30/40 (230-30') # SM# 30/40 (230-30') # SM# 30/40 (230-30') # SM# 30/40 (230-30')		- Se	ed of scatooth collor scaling nipple - No ficial record
21.5	PBTD = 6383'	CMT W/3505	er Guirtiensth wol 690GEL 05x Quirtiensth went
	e energy of the second of the	e de la companya de l	্ত্ৰ বিভাগ কৰিব কৰিব কৰিব কৰিব কৰিব কৰিব কৰিব কৰিব
		- · · · · · · · · · · · · · · · · · · ·	