

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

GPO : 1976 O - 214-148

ABANDONMENT COPY

Rig up and trip tubing, check for bad tubing

Spot 25 sacks cement @ 6400-6213' (25 cu. ft. X 7.6' fill up per sack = 190 ft. plug

Circulate hole and spot 9.5# mud from 6213' to surface

Spot 25 sacks cement 50' below top of Gallup @ 5404' (25 cu. ft. X 7.6' fill up sack = 190' plug)

Spot 25 sacks cement 50' below top of M. V. @ 2734' (25 cu. ft. X 7.6' fill up sack = 190' plug)

Spot 25 sacks cement 50' below top of Picutre Cliffs @ 1804' (25 cu. ft. X 7.6' fill up sack = 190' plug)

D. V. tool was set @ 2004' cemented with 75 sacks + 4% Gel

Free point and pull recoverable 5 1/2" casing

Spot 35 sacks cement 50' in 5 1/2" casing stub, this should over flow for 75' plug above casing stub

Spot 60 sacks cement 50' below the top of Ojo-Alamo @ 660' (60 cu. ft. X 1.8' fig. on 10" hole = 108' plug)

Spot 60 sacks cement 50' below the bottom of 10-3/4" casing @ 311' (60 cu. ft. X 1.8' = 108' plug 351-243')

Cut 10-3/4" surface pipe off 4' below ground level (irrigation area no marker required)

Mix and spot 10 sacks cement in top of pipe

Level out well site and clean up all debris.

As stated in our letter dated 5-9-83 after talking with Mr. Jack Myrick and Mr. Vernon Cohoe with N.I.I.P. we can not commence plugging procedures until their crops are gathered from around this well site.

* Move the plug over the top of the Ojo Alamo down hole to cover the bed boundary at the bottom of the said formation (from 50' below to 50' above bed boundary).