

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		MAY 06 1985	
2. NAME OF OPERATOR El Paso Natural Gas Company		BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA	
3. ADDRESS OF OPERATOR P.O. Box 4289, Farmington, New Mexico 87499		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1840'S, 1500'E of Sec. 25, T-28-N, R-8-W		8. FARM OR LEASE NAME Russell	
14. PERMIT NO.		9. WELL NO. #7	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6218' GL		10. FIELD AND POOL, OR WILDCAT South Blanco PC	
		11. SEC., T., R., E., M., OR BLK. AND SURVEY OR AREA SE 25, T-28-N, R-8-W	
		12. COUNTY OR PARISH San Juan	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PLUG OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Procedure to Plug and Abandon

- 1) Move on location. Pick up 1 1/4" work string. Circulate wellbore.
- 2) Spot 25 sx (29.50 cu. ft.) cement plug from 2133' to 2859'.
- 3) Perforate 2 squeeze holes at 1900'.
- 4) Spot 25 sx (29.50 cu. ft.) cement plug from 1224' to 1950'.
- 5) Perforate 4 squeeze holes at 146'.
- 6) Circulate 45 sx (53.10 cu. ft.) from 146' to the surface leaving both the inside and outside of the casing full of cement.
- 7) Cut off the wellhead and install the dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED John J. Tellerson

TITLE Production Engineer

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

APPROVED

DATE May 3, 1985

MAY 06 1985

AREA MANAGER
FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side

NMOCC