

N. OF COPIES RECEIVED	3
DISTRIBUTION	
OFFICE	
DATE	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
V-89	

SUNDRY NOTICES AND REPORTS ON WELLS

NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator Resources Investment Corporation		8. Farm or Lease Name Dietrich State
3. Address of Operator Suite 2080, First of Denver Plaza, 633 17th St., Denver, CO 80202		9. Well No. 1
4. Location of Well UNIT LETTER K 2470 FEET FROM THE south LINE AND 1580 FEET FROM THE west LINE, SECTION 16 TOWNSHIP 27N RANGE 12W NMPM.		10. Field and Pool, or Wildcat Basin Dakota
15. Elevation (Show whether DF, RT, GR, etc.) 5784 GL		12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Fracture treatment
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rig up pulling unit, run cement bond log and Gamma Ray-Neutron log. Perforate Dakota 6003-6011. Acidize with 500 gallon 15% acid and swab test. No production. Run cast iron bridge plug and set at 5995'. Perforate Dakota 5914-32, 5857-60, 5868-70, 5902-09 with one jet shot per foot. Acidize with 1500 gallon 15% acid and ball sealers. Fracture with 2336 barrels complex gel water with 10,000# 100 mesh sand and 103,400# 20-40 sand. Average injection rate 20 barrels per minute, average pressure 2300 psi, instant shut in pressure 1900 psi.

Now flowing to pit to recover load and test.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>John Alexander</u>	TITLE <u>Agent</u>	DATE <u>8-18-77</u>
Original Signed by A. R. Kendrick		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		