Form 3160-5 (June 1990)

Approved by

Conditions of approval, if any:

representations as to any matter within its jurisdiction.

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  Use "APPLICATION FOR PERMIT - " for such proposals		5. Lease Designation and Serial No.  SF-078329  6. If Indian, Allottee or Tribe Name  7. If Unit or CA, Agreement Designation	
<b>~</b> :			
1. Type of Well			
Oil Gas Other		8. Well Name and No.  Daum LS #6E	
2. Name of Operator			
Amoco Production Company	Amoco Production Company Mike Curry		
3. Address and Telephone No.		3004526543	
P.O. Box 800, Denver, Colorado 80201	P.O. Box 800, Denver, Colorado 80201		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Basin DK Gas/Otero-Chacra-Gas	
		11. County or Parish, State	
700' FNL 1600' FEL	Sec. 32 T 28N R 9W NW/4NE/4	San Juan New Mexico	
		00.1 00.1	
12. CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOT	TICE , REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF		
Notice of Intent  Subsequent Report  Final Abandonment Notice	Abendonment Recompletion Plugging Back Casing Repair Altering Casing Other Packer Repair	Change of Plans  New Construction  Non-Routine Frecturing  Water Shut-Off  Conversion to Injection  Dispose Water  (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
Please see attached.  DEC = 2 19  OIL CON.	93. DIVJ		
14.1 hereby certify that the foregoing is true and correct	<b>D</b>	siness Analyst Dre 11-16-1993	

\* See Instructions on Reverse Side

Title

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States as

# PROCEDURE FOR PACKER REPAIR DAUM LS 6E BASIN DAKOTA - DAKOTA/CHACRA SRBU - SAN JUAN OC November 15, 1993

Purpose:

This Dual Dakota/Chacra well has a packer isolating the two producing zones. The packer was found to be leaking in the latest packer integrity test. It should be replaced to comply with environmental regulations.

Please call Stan Kolodzie at ext. 4769 in Denver if you have any questions.

Current Production:

Estimated Cost:

110 MCFD

\$ 17,000

Anticipated Production

Estimated Payout:

110 MCFD

NA -- Environmental

### REQUIRED PERMITS AND APPROVALS BEFORE WORKOVER CAN BEGIN (Check off as permits are received)

**BLM** 

Surface Disturbance - No Permit Required No surface disturbance is anticipated.

<> Wellbore Changes - No Permit Required No wellbore changes are anticipated.

<> Produced Fluids - No Permit Required Produced fluids will be handled as before the workover.

DEQ

Surface Discharge - No Permit Required No surface discharge is anticipated

NOTES:

Well Plac OC = 00

Well Flac No. = 97987501-0

Elev. Reference: 6315 GL

97987502**-8** 

API 3004526543

Amoco WI = 0.500

Lease 698974-00

5T/7TUS

CE#3C 610117-

WORKOVER BILLING CODE: STATUS 30

Packer Repair Daum LS 6 E November 15, 1993

#### Procedure:

- 1. Move in rig. Rig Up. Nipple up blowout preventer.
- 2. Kill well.
- 3. Pull Chacra 1 1/4" tubing string.
- 4. Pull Dakota tubing string.
- 5. Run mill. Mill out packer slips. Retrieve Model D packer and Dakota bottom hole assembly.
- 5. Run 7" bit and scraper to top of 4 1/2" liner at 3589'.
- 6. Run new or rebuilt Model D packer and BHA. Set packer at 3577' (or some other depth 10' or more from the previous packer setting depth of 3587'). Bottom of tubing should be at 6858' (Top of Dakota perfs). Rerun Dakota tubing with seating nipple. Set seal assembly into Model D.
- 7. Run 1 1/4" Chacra tubing with seating nipple. Land tubing at 3400'or nearest joint.
- 8. Nipple down BOP. Nipple up Wellhead.
- 9. Swab in well. Return to production.
- 10. Obtain producing pressures on the Chacra and Dakota sides to show that the packer is isolating the horizons from each other.

AUTHORIZATIONS	ENGINEER	Stank	Kely	
PRODUCTION				
	OVER FOREMA	AN	ر ر	

cc: B X Maez, K A Sauvageau} SJOC S X Kolodzie, M P Curry, Well File } Denver

#### PACKER REPAIR DAUM LS 6E November 15, 1993 MATERIALS LIST

#### <u>Amoco</u>

Service Unit with Rig Pump Bit and Scraper for 7", 23#, K-55 casing Model D Packer for 7", 23#, K-55 casing Swab unit

#### <u>Vendor</u>

None

DAUM LS 006E 2402 Location — 32B—28N—9W DUAL dk—ck Orig.Completion — 01/86 Last File Update — 1/89 by JSF USA SF-078329

