

Form 9-321  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 077978-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Dugan Production Corp.

3. ADDRESS OF OPERATOR

Box 234, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

990' FSL - 990' FEL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Douthitt

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated - Gallup

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 33, T28N, R13W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5974' DF

12. COUNTY OR PARISH 13. STATE

San Juan

NM

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐  
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL


ALTERING CASING

ABANDONMENT\*

☒  
☐  
☐  
☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

Repaired casing leak as follows:

1. Washed over and pulled stuck tubing
2. Set bridge plug above perms at 5326'
3. Located hole at 3212', squeezed with 150 sx neat cement
4. Drilled out cement and pressure tested casing OK, drilled bridge plug, and cleaned out to 5540'
5. Re-ran tubing and rods and put well back on production



18. I hereby certify that foregoing is true and correct

SIGNED

Original signed  
Jim L. Jacobs

TITLE

Geologist

DATE

6-11-74

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: