Form 3160-5 (August 1999)

# UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED
OMB MO. 1004-0135
Expires: November 30, 200

SUNDRY NOTICES AND REPORTS ON VEILS  Do not use this form for proposals to drill or to be enter an abandoned well. Use form 3160-3 (APD) for such proposition 2001  SUBMIT IN TRIPLICATE - Other instructions on several side.		5. Lease Serial No. NMSF-078828A  6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instru	7. If Unit or CA/Agreement, Name and/or No.	
Type of Well	0/67.3	8. Well Name and No. GALLEGOS CANYON UNIT 13
2. Name of Operator Contact: AMOCO PRODUCTION COMPANY	CHERRY HOWA E-Mail: hlavad abb. comy	9. API Well No. 30-045-07100
3a. Address P.O. BOX 3092 HOUSTON, TX 77253	3b. Phone No. (include area code) Ph: 281.366.4081 Fx: 281.366.0700	10. Field and Pool, or Exploratory BASIN FRUITLAND COAL
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, and State
Sec 27 T28N R12W Mer SWSW 660FSL 660FWL		SAN JUAN COUNTY, TX
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		

#### TYPE OF ACTION TYPE OF SUBMISSION □ Water Shut-Off ☐ Production (Start/Resume) □ Acidize Deepen ■ Notice of Intent ☐ Fracture Treat ■ Well Integrity ☐ Alter Casing ☐ Reclamation ☐ Subsequent Report Casing Repair ☐ New Construction ☐ Recomplete □ Other ☐ Final Abandonment Notice □ Change Plans ☑ Plug and Abandon □ Temporarily Abandon

☐ Plug Back

■ Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Amoco Production Company requests permission to plug and abandon the subject well as per the attached procedure.

□ Convert to Injection

Should you have any technical questions please contact Allen Kutch @281-366-7955. For administrative concerns please contact Cherry Hlava @281-366-4081

14. I hereby certify that the foregoing is true and correct.  Electronic Submission #7287 verified before AMOCO PRODUCTION COM Committed to AFMSS for processing the committed	PANY, sent to the Farmington		
Name (Printed/Typed) CHERRY HLAVA	Title AUTHORIZED REPRESENTATIVE		
Signature Date 09/20/2001  THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
	Title Date 11/15/01		
certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## SJ Basin Well Work Procedure

Well Name: GALLEGOS CANYON UNIT #13

Version:

Date: SEPTEMBER 19, 2001

**Budget:** 

Repair Type: PLUG & ABANDON

**SAP Code:** 

### Objective: P&A WELL

1. TOH and strap 1446' 2 3/8".

2. Set cement plugs.

3. Cut off wellhead & install dry hole marker.

#### **Pertinent Information:**

Location: T28N-R12W-Sec27 API #: 30-045-07100

County: San Juan FlacWell: State: New Mexico Engr:

Horizon: Fruitland Coal

#### Procedure:

- 1. Check anchors. MIRU.
- 2. Check and record tubing, casing, and bradenhead pressures.
- 3. Blow down well. If necessary, kill with fresh water.
- 4. Nipple down WH. NU BOPs. Pressure test to 500 psi.
- 5. TOH and strap 1446' of 2 3/8" tbg.
- 6. RU wireline and set 7" CIBP at 1400'. TIH with tbg open ended to 1400'.
- 7. Pressure test csg to 500 psi for 15 minutes. Plug #1 (1300' 1400'), balance 20 sx Cl. B cement inside csg. TOH.
- 8. RU wireline and perforate squeeze holes at 194'.

- 9. Plug #2 (0' 194'), mix approximately 78 sx Cl. B. cement to circulate good cement to surface.
- 10. ND BOP & dig cellar. Cut off wellhead and top off casings as needed.
- 11. RD rig. Remove deadmen. Install dry hole marker.
- 12. Restore location as per BLM requirements.