Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135

(December 1989) Expires: September 30, 1990 **BUREAU OF LAND MANAGEMENT** 5. Lease Designation and Serial No. SUNDRY NOTICES AND REPORTS ON WELLS I-149-IDN-8470 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. 6. If Indian, Allottee or Tribe Name Use "APPLICATION FOR PERMIT--" for such proposals." 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well OIL WELL 8. Well Name and No. **OTHER** Gallegos Canyon Unit 319 2. Name of Operator 9. API Well No. Amoco Production Company Melissa Velasco 30-045-25990 3. Address and Telephone No. 10. Field and Pool, or Exploratory Area P.O. Box 3092 Houston, TX 77253 (281) 366-2548 **Kutz West Pictured Cliffs** 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 1520' FNL 1400' FWL Sec 30 T28N R12W San Juan New Mexico CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12 TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion **New Construction** Subsequent Report Plugging Back Non-Routine Fracturing Final Abandonment Notice Casing Repair Water Shut-Off Altering Casing Conversion to Injection X Other **BLM Letter 09/10/1999** (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Amoco Production Company request permission to plug and abandon the subject well as per the attached well work procedure.

14. I hereby certify that the foregoing is true and correct Signed Title Permitting Staff Assistant	Date03/20/00
(This space for Federal or State office use)	
Approved by (S) Charles Beachern Title	AFA − 5 1
Conditions of approval, if any:	Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

SJOET Well Work Procedure

Well:

GCU 319

Version:

#1

Date:

March 15, 2000

Budget:

DRA

Repair Type:

PXA

SAP Project #:

X7-000G0

Objectives:

1. To PXA the entire well.

Pertinent Information: Location:

F30 T28N-R12W, 1520' FNL, 1400' FWL

Horizon:

PC

County:

San Juan

API #:

3004523995 Allen Kutch

State:

New Mexico

Engr:

Lease:

I-149-IND-8470

Phone:

W (281) 366-7955

Well Flac: 886630 Lease Flac: 190381

Economic Information:

APC WI:

51.8%

Estimated Cost:

\$7,500

Formation Tops: (NMOCD estimated formation tops)

San Jose:

Menefee:

Nacimento:

Point Lookout:

Oio Alamo:

Mancos Shale:

Kirtland Shale:

Gallup:

Fruitland:

250 1114

Graneros:

Pictured Cliffs: 1410

Dakota:

Lewis Shale:

Morrison:

Chacra:

Cliff House:

Bradenhead Test Information:

Test Date: 11/6/97 **Tubing**: 0 Casing: 220 **BH**: 0

Time	ВН	CSG	INT	CSG
5 min	0	220	<u> </u>	
10 min	0	220		
_15 min	0	220		

Comments:

Well shut-in.

GCU 319

Original Completion: 8/81 Recompletion: 3/95

TD = 1,595' PBTD = 1,545'

Objective: PXA entire wellbore (including Pictured Cliffs and Fruitland Coal)

Page 2 of 2

1. Notify regulatory agencies (BLM, NMOCD, FIMO) 24 hours in advance of plugging activity. Contact BLM and indicate well is allotted (FIMO regulations effective April 1, 1997).

- 2. Check location for anchors. Install if necessary. Test anchors.
- 3. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 4. TOH with 2 3/8" tubing, remove mud anchor. TIH with 2 3/8" tubing workstring and CIBP. Set CIBP at 1,400'. Spot cement plug from 1,400' to 1,064' (26 sacks). TOH to 300', spot cement plug from 300' to surface (23 sacks).
- 5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Contact FMC and ship surface equipment to yard or other location per instructions.
- 7. Provide workorder to Buddy Shaw for reclamation.
- 8. Rehabilitate location according to BLM or State requirements.

GCU 319 (FT)

F30 T28N-R12W, 1520 FNL, 1400 FWL API 3004524990 I-149-IND-8470

Proposed PXA Wellbore Schematic

