SUBMIT IN TRIPLICATE. UNITED STATES

Form approved. Budget Bureau No. 42 R1424.

(51ay	DEPARTMENT OF THE INTERIOR TOTTLE TOT				SF 078426		
	SUNDRY On the state of the stat	NOTICES AND RE	PORTS oen or plug or such p	ON WELLS back to a different reservoir. proposals.)	6. IF INDIAN, ALLOTTS	E OR TRIBE NAME	
1. 01: W1		7. UNIT AGREEMENT NAME San Juan 29-6 Unit					
2. N	AME OF OPERATOR	8. FARM OR LEASE NAME					
3 45	El Paso Natural Ga	San Juan 29-6 Unit 9. WELL NO.					
4. 1.6 Se		nington, NM 87401 cation clearly and in accordant 1150'S, 1650'W	s State requirements.•	10. FIELD AND POOL, OR WILDCAT Blanco Mesa Verde 11. SEC., T., R., M., OR BLA. AND SUBVEY OR AREA			
					Sec. 17, T-29-N, R-6-W		
14 p	ERMIT NO. 15. ELEVATIONS (Show whether			F, RT, GR, etc.)	12, COUNTY OR PARIS	H 13. NTATE	
17. 1	philip 101		6716'DF			New Mexico	
16.	Che	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data					
	• • •				EQUENT REFORT OF:		
:	TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS	x	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other)	REPAIRING ALTERING ABANDONM	CASING ENT*	
	(Other) Constitue proposed or completed of Recompletion on Well Completion of Recompletion on Report and Log form. 17. Describe proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) During workover in 1954, a fish was left in the open hole with top of fish at 5386'. Well has not produced since 1954. It is planned to plug and abandon the well in the following manner: Spot a 50 sk. cement plug in the open hole section (fills open hole and up to 5000' inside the casing). Perforate squeeze holes and spot a 60 sk. cement plug at the base of the Ojo Alarge 1819 Squeeze 40 sks. of cement through holes into the casing annulus. Cut off casing at the free point and spot a 50 sk. cement plug on the casing stup.						
•							
	Spot a 25 sk. cement plug at the base of the surface pipe.				01	L CON. COM. DIST. 3	
	Place a 15 sk. cement plug at the surface. Install a dry hole marker and clean up the location.						

TITLE Petroleum Engineer

ing is true and correct

REPROVED BY CONDITIONS OF APPROVIL, IF ANY:

1972

FONG