State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

| Sundry Notices and Reports on Wells | |
|---|---|
| | API # (assigned by OCD) |
| 1 Marie of Wall | 30-039-07657 |
| 1. Type of Well GAS | 5. Lease Number FEE |
| | 6. State Oil&Gas Lease # |
| 2. Name of Operator | 7. Lease Name/Unit Name |
| BURLINGTON | |
| RESOURCES OIL & GAS COMPANY | San Juan 29-7 Unit 8. Well No. |
| 3. Address & Phone No. of Operator | #80 |
| PO Box 4289, Farmington, NM 87499 (505) 32 | 6-9700 9. Pool Name or Wildcat |
| A Togetier of Well Books of B. W. | Blanco Mesaverde |
| 4. Location of Well, Footage, Sec., T, R, M 1650' FSL, 1650' FWL, Sec. 9, T-29-N, R-7-W, | 10. Elevation: |
| 1650 FSL, 1650 FWL, Sec. 9, 1-29-N, R-7-W, | NMPM, RIO Arriba County |
| Type of Submission Typ | e of Action |
| X Notice of Intent Abandonmen | |
| Recompleti | |
| Subsequent Report Plugging B | |
| Casing Rep | |
| | asing Conversion to Injection |
| X_Other - Tubing repair | |
| It is intended to repair the tubing on the attached procedure. | e subject well according to the |
| | DECEIVED NUL 1 0 1998 |
| | OIL COM. DIV. DIST. 3 |
| SIGNATURE MAY MAN LUCK (LTL8) RO | egulatory AdministratorJune 5, 1998vkh |
| (This space for State Use) Sharing Rollinson Approved by Title | JUN 1 () 1998 PUTY OIL & GAS INSPECTOR, DIST. #3 Date |

San Juan 29-7 Unit #80 Blanco Mesaverde

Unit K, Sec. 09, T-29-N, R-07-W Latitude / Longitude: 36° 44.26938' / 107° 34.76532'

Recommended Tubing Repair Procedure 5/21/98

NOTE: ALL DEPTHS ARE MEASURED FROM KB. KB to GL was 8'.

- 1. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Prior to moving in rig, make one-call and then verify rig anchors and dig pit.
- MIRU workover rig. NU relief line and blow well down (kill with 2% KCL water only if necessary). ND WH and NU BOP. Test and record operation of BOP rams. Replace any WH valves that do not operate properly. Test secondary seal and install or replace if necessary.
- 3. Mesaverde, 2-3/8", 4.7#, J-55 tubing set at 5593' (176 jts). Broach tubing and set tubing plug in nipple at 5561' (1-25/32" ID). Fill tubing with half of its volume of 2% KCL to insure the tubing plug will be held in place. Release donut, pick up additional joints of tubing and tag bottom, recording the depth. PBTD should be at +/- 5680'. TOOH and stand back 2-3/8" tubing. Visually inspect tubing for corrosion, and replace any bad joints. Check tubing for scale and notify Operations Engineer if it is present.
- 4. TIH with 3-7/8" bit, bit sub, and watermelon mill on 2-3/8" tubing and round trip to PBTD, cleaning out with air/mist. NOTE: When using air/mist, mist rate must not be less than 12 bph. Speak with Operations Engineer, and if necessary, determine the best way to remove scale from the casing and perforations.
- 5. TIH with one joint of 2-3/8" tubing with expendable check, F-nipple (one joint off bottom), then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist.
- 6. PU above the top Mesaverde perforation at **4755'** and flow the well naturally, making short trips for clean-up when necessary. Obtain pitot gauge from casing and report this gauge after final clean-up.
- 7. Land tubing at **5460**'. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. If well will not flow on its own, make swab run to SN. RD and MOL. Return well to production.

Recommended: 4 Jon Jovet Approved: Bruch Bond 6-1-95
Operations Engineer 5/21/98
Approved: Bruch Bond 6-1-95
Drilling Superintendent

Contact:

L. Tom Loveland

Office 326-9771 Pager 324-2568 Home 564-4418