## UNITED STATES

## DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT WED

Cundry Not	ices and Reports on Wells.		
Sundry Not.	93 JUN -5 PN 3: 12		
1. <b>Type of Well</b> GAS	070 FARELINGTON, NM	5. 6.	SF-078423
2. Name of Operator  BURLINGTON		7.	Unit Agreement Name San Juan 29-7 Unit
3. Address & Phone No. of Opera			Well Name & Number San Juan 29-7 U #86 API Well No.
PO Box 4289, Farmington, NM 87499 (505) 326-9700  4. Location of Well, Footage, Sec., T, R, M  1850' FSL, 905' FWL, Sec. 17, T-29-N, R-7-W, NMPM		10.	30-039-07617 <b>Field and Pool</b> Blanco Mesaverde
		11.	County and State Rio Arriba Co., NM
12. CHECK APPROPRIATE BOX TO INTERPORT TYPE of Submission  _X_ Notice of Intent  Subsequent Report  Final Abandonment	Type of Action  Abandonment Change Recompletion New Co Plugging Back Non-Ro Casing Repair Water Altering Casing Conver X Other - Tubing repair	of Planstructutine I	ans tion Fracturing Ef
It is intended to repair attached procedure.	the tubing on the subject well a	ccordin	
	DECE N Jun 1	n n n	_
	OIL GON Dist.	. DIT	%
$\mathcal{A}$	foregoing is true and correct.  7 LTL) Title Regulatory Administra		te 6/3/98
(This space for Federal or State			JUN 0 9 ;
CONDITION OF APPROVAL, if any:		-	JUH OS PRO

## San Juan 29-7 Unit #86 Blanco Mesaverde

Unit L, Sec. 17, T-29-N, R-7-W

Latitude / Longitude: 36°43.44180' / 107° 35.99946' Recommended Tubing Repair Procedure 5/20/98

NOTE: ALL DEPTHS ARE MEASURED FROM KB. KB to GL was 10'.

- Comply with all NMOCD, BLM and Burlington safety and environmental regulations.
   Prior to moving in rig, make one-call and then verify rig anchors and dig pit.
- MIRU workover rig. NU relief line and blow well down (kill with 2% KCL water only if necessary). ND WH and NU BOP. Test and record operation of BOP rams. Replace any WH valves that do not operate properly. Test secondary seal and install or replace if necessary.
- Mesaverde, 2-3/8", 4.7#, J-55 tubing set at 5975' (197 jts). Broach tubing and set tubing plug in nipple at 5974'. Fill tubing with half of its volume of 2% KCL to insure the tubing plug will be held in place. Release donut, pick up additional joints of tubing and tag bottom, recording the depth. PBTD should be at +/- 6022'. TOOH and stand back 2-3/8" tubing. Visually inspect tubing for corrosion, and replace any bad joints. Check tubing for scale and notify Operations Engineer if it is present.
- 4. TIH with 3-7/8" bit, bit sub, and watermelon mill on 2-3/8" tubing and round trip to PBTD, cleaning out with air/mist. NOTE: When using air/mist, mist rate must not be less than 12 bph. Speak with Operations Engineer, and if necessary, determine the best way to remove scale from the casing and perforations.
- 5. TIH with one joint of 2-3/8" tubing with expendable check, F-nipple (one joint off bottom), then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist.
- 6. PU above the top Mesaverde perforation at **5250'** and flow the well naturally, making short trips for clean-up when necessary. Obtain pitot gauge from casing and report this gauge after final clean-up.
- 7. Land tubing at 5912'. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. If well will not flow on its own, make swab run to SN. RD and MOL. Return well to production.

	Bruce (). Boya Drilling Superintender	6-1-95
--	--	--------

Contact:

L. Tom Loveland

Office 326-9771 Pager 324-2568

Home 564-4418