State of New Mexico Submit 3 Copies Form C-103 Energy, Minerals and Natural Resources Department to Appropriate Revised 1-1-89 District Office DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION WELL API NO. P.O.Box 2088 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 30 045 07976 Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 STATE FEE 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" 7. Lease Name or Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Trujillo Gas Com OIL WELL GAS WELL X OTHER 2. Name of Operator 8. Well No. Amoco Production Company 1 Attn: John Hampton 3. Address of Operator 9. Pool name or Wildcat P.O. box 800, Denver, Colorado 80201 Aztec Pictured Cliffs 4. Well Location Unit Letter : 1080 Feet From The South Line and 970 Feet From The West Line Section Township 29N Range 10W **NMPM** San Juan County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5493' RDB 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **ALTERING CASING TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Amoco Production Company intends to Plug and Abandon the subject well. See attached for procedure: OCT1 3 1992 OIL CON. DIV. If you have any questions please call Julie Acevedo at 303-830-6003.

I hereby certify that the information above is true and complete to the best of my	knowledge and belief	
TYPE OR PRINT NAME Julie Acevedo	mme Sr. Staff Assistant	DATE] <u>0/7/92</u>
(This space for State Use)		TELEPHONE NO. 303-830-6003
Original Signed by CHARLES GHOLSON	TITLE DEPUTY ON & GAS INSPECTOR, DIST. #3	OCT 13 1992
CONDITIONS OF ADDIOUGH IN ANIX		- DATE

PXA Procedures Trujillo Gas Com #1 21M-29N-10W

- Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. NDWH. NUBOP. Blow down well. Kill if necessary with fresh water.
- Get injection rate under packer at 1725' and monitor backside. Monitor 24hrs. If no change squeeze perfs thru tubing at 1764' to 1786' with 23 class B cement.
- One joint above pkr cut and pull tbg. Spot 4 sx class B cement on top of pkr. WOC. Tag top of cement.
- 5. Run CBL to determine TOC.
- 6. RIH with 2 3/8" bit and scraper RIH with tbg and pkr. Set pkr at 1000'. Squeeze perfs at 1050' to 1070' with 23 sx class B cement. Pull out of pkr and spot 4 sx class B cement on top.
- 7. RIH with perforating gun and shoot squeeze holes 50'above TOC.
- 8. RIH with tbg and retainer/pkr. Set retainer/pkr above the perfs and attempt to circulate to surface thru the squeezes holes with 200 sx class B cement. (100% excess)
- 9. Pull out of retainer/pkr and set a cement plug to surface with 150 sx class B cement. (50% excess)
- 10. NDBOP. Cut of casing and wellhead. Install PXA marker according to BLM or State requirements.
- 11. Turn over to John Schwartz for reclamation.
- 12. Rehabilitate location according to BLM or state requirements.

