

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DC, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 300450841300
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Bruington Gas Com B
2. Name of Operator Amoco Production Company Attn: John Hampton	8. Well No. 1
3. Address of Operator P.O. Box 800, Denver, Colorado 80201	9. Pool name or Wildcat Basin Dakota
4. Well Location Unit Letter <u>A</u> : <u>790</u> Feet From The <u>North</u> Line and <u>840</u> Feet From The <u>East</u> Line Section <u>15</u> Township <u>29N</u> Range <u>12W</u> N.M.P.M. <u>San Juan</u> County	
10. Elevation (Show whether OF, RKB, RT, GR, etc.) <u>5625' RDB</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <u>Repair Casing Leak</u> <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Amoco Production Company intends to Repair casing leak see attached for procedure:

**RECEIVED**  
MAR 05 1990  
OIL CON. DIV.  
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE <u>John Hampton</u>	TITLE <u>Sr. Staff Admin. Supv.</u> DATE <u>3/1/90</u>
TYPE OR PRINT NAME <u>John Hampton</u>	TELEPHONE NO.

(This space for State Use)

APPROVED BY Original Signed by FRANK T. CHAVEZ SUPERVISOR DISTRICT 3 DATE MAR 05 1990

CONDITIONS OF APPROVAL, IF ANY:

*Placed in unit, as usual. To be consistent with file, number 16*

RECEIVED  
MAR 17 1964  
U.S. AIR FORCE  
HEADQUARTERS  
WASHINGTON, D.C.

MAR 17 1964

U.S. AIR FORCE

BRUINGTON GC B #1  
BASIN DAKOTA

CASING REPAIR PROCEDURE  
-----

1. Check location for anchors. Install if necessary. Test anchors.
2. MIRUSU. Blow well down. Kill if necessary w/ 2% KCl.  
NDWH. NUBOP.
3. RIH & TAG FOR FILL. TALLY OOH W/TBG. TIH W/ 3 7/8" BIT AND  
SCRAPER (DRIFT I.D. OF CSG. IS 3.927") POOH. RIH W/RETRIEVABLE  
bridge bridge plug and pkr. Set RBP approx. 100' above the  
perforations. Pull 1 std and pressure test RBP to 2000 psi.  
Load backside and PT to 750# to confirm leak. NOTIFY THERESA  
WISDA IMMEDIATELY (X4587) IF THERE IS A LEAK!!!!
4. Isolate leak. Once leak is located, PT the backside. If backside  
holds, procede to step #5 after spotting 2 sacks of sand on  
top of the RBP. If backside leaks, continue POOH and pressure  
testing the backside to isolate upper leak. After locating the  
leak, spot 2 sx. sand on top of RBP. TOH w/pkr. Procede with steps  
5-7 for each leak starting with the lowest leak first. (If a large  
section of casing is bad, spot cement across the section and do  
a bradenhead squeeze.)
5. Establish rate into leak with fresh wtr. If rate can not be  
established into leak, shoot squeeze holes. SQ w/a minimum of 75  
sx Class B 2% CaCl (Put .6% D60 for fluid loss in first 75% of the  
sx) Use more cement if necessary. Do not exceed 1500# squeeze  
pressure. Rev. circ. off of pkr. WOC 24 hrs.
6. RIH W/ 3 7/8" BIT AND CSG SCRAPER. DRILL OUT CMT. PT CSG. TO 750#.  
POOH.
7. Swab test the cement squeeze. Re-squeeze if necessary.
8. RIH w/tbg and retrieving head. Clean out to RBP w/foam. Release  
RBP and POOH.
9. If fill was encountered, procede with sand clean out according  
to the attached procedure beginning with step 5. If no fill, RIH  
AND LAND TBG AT 6232'.
10. NDBOP. NUWH. Kick well around w/nitrogen if well had casing leak  
or a sand clean out was performed. Otherwise, swab well in. (If  
more than one day of swabbing is required, release rig and call in  
wireline swabbing unit.)