

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.
NM- 02989

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

AMOCO PRODUCTION COMPANY

Contact: CHERRY HLAVA
E-Mail: corleyml@bp.com8. Well Name and No.
JOHNSON GAS COM C 19. API Well No.
30-045-08611

3a. Address

P.O. BOX 3092
HOUSTON, TX 77253

3b. Phone No. (include area code)

Ph: 281.366.4081
Fx: 281.366.070010. Field and Pool, or Exploratory
BASIN DAKOTA

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 7 T29N R12W NENW 930FNL 1700FWL

11. County or Parish, and State
SAN JUAN COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Amoco Production Company requests permission to do a bradenhead repair on the above well per the attached procedure.

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #9013 verified by the BLM Well Information System
For AMOCO PRODUCTION COMPANY, sent to the Farmington
Committed to AFMSS for processing by Lucy Bee on 11/16/2001 ()

Name (Printed/Typed) CHERRY HLAVA

Title AUTHORIZED REPRESENTATIVE

Signature (Electronic Submission)

Date 11/15/2001

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By /s/ Jim Lovato

Title

Date MAY 28

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL **

NMOCD

San Juan Basin Well Work Procedure

Well Name: Johnson Gas Com C 1
Version: #1
Date: 11/14/2001
Budget: DRA
Repair Type: Bradenhead Type 1

Objectives:

1. Repair bradenhead.
-

Pertinent Information:

Location:	Sec 7 of T29N – R12W	Horizon:	Dakota
County:	San Juan	API #:	30-045-086110
State:	New Mexico	Engr:	Allen Kutch
Lease:		Phone:	(281)366-7955
Well Flac:	92422701		
Lease	290469		
Flac:			

Economic Information:

APC WI: 0.6265
Estimated Cost: \$45,000

Production rate: 40 mcf/d

Formation Tops: (Estimated formation tops)

Nacimiento:		Menefee:	3235
Ojo Alamo:		Point Lookout:	3964
Kirtland		Mancos	4288
Shale:		Shale:	
Fruitland:	1300	Gallup:	5211
Pictured	1554	Graneros:	6012
Cliffs:			
Lewis Shale:		Dakota:	6061
Chacra:		Morrison:	
Cliff House:	3110		

Bradenhead Test Information:

Test Date:	8/9/200	Tubing	233	Casing	466	BH	106
	0	:		:		:	
Time	BH	CSG	INT	CSG			
5 min							
10 min							
15 min							

Comments: BH blew down TSTM. BH shut-in for 5 minutes after flow – psi was 12 and csg was 464.

Bradenhead Repair Procedure - Type 1 (2 strings of casing)

1. Contact State agency prior to starting repair work (NMOCD Charlie Perrin, 505-334-6178 X16).
2. Check location for anchors. Install if necessary. Test anchors.
3. Catch gas and/or water sample off of bradenhead and casing for analysis.
4. MIRUSU. Check and record tubing, casing and bradenhead pressures.
5. Blow down well and kill well, if necessary, with 2% KCL water.
6. ND wellhead. NU and pressure test BOP's.
7. TIH and tag 6275' PBTD, check for fill. Trip and tally out of hole with tubing, checking condition of tubing.
8. TIH with bit and scraper to top of perforations. A seating nipple and standing valve may be run in order to pressure test tubing. TOH.
9. TIH with RBP and packer. Set RBP 50 - 100 feet above perforations. Pressure test csg to 500 psi.
10. Swab fluid off of RBP. Re-set RBP at +/- 2000'. Re-test csg to 500 psi. Dump sand on top of RBP.
11. Log CBL/CCL from 1500' – 250' to determine cement top.
12. Perforate casing above cement top, if necessary, with 4 JSPF and determine cement volume.
13. Mix and pump sufficient cement (Class B or equivalent, with a setting time of 2 hours) to circulate to surface. Shut bradenhead valve and attempt to walk squeeze to obtain a 1000 psi squeeze pressure. WOC.
14. TIH with bit and scraper and drill out cement. Pressure test casing to 500 psi. TOH with bit and scraper.
15. TIH with retrieving head for RBP. Circulate sand off of RBP. Swab fluid off of RBP and retrieve RBP.
16. TIH with sawtooth collar and/or bailer and clean out hole to PBTD, if fill was found in step 7. TOH.
17. TIH with production string and land tubing at 6130'. NDBOP. NU wellhead.
18. Swab well in and put on production.
19. RDMOSU.