

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

USA-078108

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

-

7. UNIT AGREEMENT NAME

-

8. FARM OR LEASE NAME

New Mexico Federal "K"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 6, T-29-N. R-14-W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Sunray DX Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 1416, Roswell, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirement.
See also space 17 below.)
At surface

990' FNL & 990' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5383' DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

Plug & Abandon ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. Present PBSD @ 5518'.

2. Top of cmt behind 5 1/2" prod. csg. @ 4025'. 8 5/8" surf. csg @ 252' w/200 sxs cmt circulated to surface. 5 1/2" prod. csg. @ 5680' w/300 sxs cmt. Perfs @ 5412-32', 5438-50', 5454-72', 5480-92' & 5500-18'.

3. Load hole w/mud.

4. Cut off 5 1/2 csg @ approx 3900. Pull prod. csg. Keep hole loaded w/mud.

5. Place 25 sxs cmt plug (5318-5518') to cover perfs.

6. Place 12 sx cmt plug in and out of 5 1/2" stub (3870'-3930').

7. Set 17 sx cmt plug in & out of 8 5/8" surf. csg. (222'-282').

8. Set 10 sx cmt plug @ surface.

9. Install dryhole marker.

10. Remove surface equipment & clean up location.

18. I hereby certify that the foregoing is true and correct

SIGNED B.F. Brawley TITLE District Engineer

DATE 11-14-66

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

*See Instructions on Reverse Side

RECEIVED

NOV 17 1966

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.