

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-10J
Revised 1-1-89

DISTRICT I
P.O. Box 1280, Hobbs, NM 88240

DISTRICT II
P.O. Drawer 60, Azusa, NM 88210

DISTRICT III
1000 Rio Grande Rd., Alamo, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-045-09369

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator
Amoco Production Company Attn: John Hampton

3. Address of Operator
P.O. Box 800, Denver, Colorado 80201

4. Well Location
Unit Letter H : 1795 Feet From The North Line and 1080 Feet From The East Line
Section 19 Township 30N Range 8W NM 117-1 San Juan County

7. Lease Name or Unit Agreement Name

Lindsey /A/ LS

8. Well No. #1

9. Pool name or Wildcat
Blanco Mesaverde

10. Elevation (Show whether OF, RKB, RP, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPS. ☐ PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐ CASING TEST AND CEMENT JOB ☐
OTHER: ☐ OTHER: Bradenhead Repair ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See attachment for procedures.

RECEIVED
OCT 07 1992
OIL CON. DIV
DIST. 3

Please contact Julie Acevedo if you have any questions. (303) 830-6003.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. L. Hampton /DMT TITLE Sr. Staff Admin. Supv. DATE 10-5-92

TYPE OR PRINT NAME John Hampton

SEE INSTRUCTIONS

(This space for State Use)

APPROVED BY Original Signed by CHARLES GHOLSON

DEPUTY OIL & GAS INSPECTOR, DIST. #3

OCT 07 1992

COPIES OF APPROVAL, IF ANY:

Lindsey /A/ LS #1

MIRUSU. Kill well w/ 100 BBLs 2% KCL WTR. NDWH. NUBOPS. PR TST BOPS 2000psi. OK. PU single & tag fill. OK. TOH w/ 150 jnts. TIH w/ scraper. TOH w/ scraper. TIH w/ ret plug on 2-3/8 TBG. Set plug 4096'. PMP 155 BBLs 2% KCL WTR to fill hole & circ out gas. PR TST CSG to 1000psi. OK. Dump sand on top of plug. TOH w/ ret hd. Chk PR. OK. NDBOP & remove TBG spool. Spear CSG. Cut off weld plate. RI WLE & run freepoint. CSG free @ 2400'. RIH w/ string shot for backoff @ 2403'. Pull & lay dwn 78 jnts CSG. TIH w/ scraper to 2375'. TOH. SIH w/ ret plug. TOH. TIH & tag tight spot 70. RU swivel & break circ. Mill. Pull mill & inspect. OK. PR TST CSG. Obtain circ up BH. Install dye. PMP 11 BBLs to obtain full circ. TIH w/ tapered mill. TOH. TIH w/ ret plug. Set plug @ 2343. TOH. Missing 3 DRL collars & ret hd for plug. Make up overshoot for collars. TIH on 2-3/8 TBG. Latch onto fish. OK. TIH w/ PKR & set @ 44'. Hole btw 44 & 134'. TOH w/ PKR. Dump sand on top of plug. RI WLE. Run CBL-VDL-GR-CCL log from 1000'-surf. Bond. RD WLE. Etab feed rate of 3 BPM @ 100psi. PMP 85 sxs oilwell + 2% CACL2. Good CMT rtns. Displace to 35'. Bit on collars. TIH. Tag CMT @ 36'. DRL CMT to 78'. Circ hole clean. PR TST CSG to 500psi. OK. PR TST BH to 500psi. OK. TOH. TIH w/ scraper to 186'. TOH. TIH w/ ret hd for ret plug. Circ sand off plug. Latch onto plug. TOH. TIH w/ DRL collars. RU swivel. Work torque to btm & rel plug. TOH w/ plug & lay dwn. Break dwn PKR. CGE pipe rams to 7". Run 72 jnts CSG. Screw in. OK. Work torque to btm. PR TST CSG to 1000psi. OK. Set slips. Cut & redress CSG. Install TBG spool w/ secondary seals. NUBOPS. TIH w/ plug ret hd. RU swivel. Rel plug. TOH w/ plug & lay dwn same. Run 150 Jnts 2-3/8 TBG. Landed @ 4670.2'. NDBOPS & NUWH. Swab. RDMOSU.