State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

Sundry Notices and Reports on Wells

	API	# (assigned by OCD) 30-045-09465
1. Type of Well GAS	5.	Lease Number
GAU	6.	
2. Name of Operator	7.	E-1641-3 Lease Name/Unit Name
BURLINGTON RESOURCES OTL 5 CAS COMPANY		
RESOURCES OIL & GAS COMPANY		Delhi Com
3. Address & Phone No. of Operator	8.	Well No. 1
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	Pool Name or Wildcat Elanco Mesaverde
4. Location of Well, Footage, Sec., T, R, M	10.	Elevation:
1650'FSL, 1650'FWL, Sec. 16, T-30-N, R-8-W, NMPM, San	ı Juan County	
Type of Submission Type of Act	ion	
X Notice of Intent Abandonment	Change of Pla	ans
Recompletion	New Construct	
Subsequent Report Plugging Back	NorRoutine 1	
Casing Repair Final Abandonment Altering Casing	_ Water Shut of Conversion to	II D Injection
X Other - Tubing rep	<u>a</u> ir	, 0002011
13. Describe Proposed or Completed Operations		
	and the state of t	and and the same of the same o
	CEIVE	
บบ	JUN 1 0 1998 -	
© [][©	l CON. D IV Diff. 3	7.
SIGNATURE Affect State Use) (This space for State Use) Approved by Johnny Robinson Title		

Delhi Com #1

Mesaverde 1650' FSL, 1650' FWL

Unit K, Section 16, T-30-N, R-08-W Latitude / Longitude: 36° 48.51' / 107° 41.02'

DPNO: 49106A **Tubing Repair Procedure**

- Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental 1. regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow 2. well down and kill with 2% KCL water if necessary. NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- Mesaverde, 2-3/8", 4.7#, J-55 tubing is set at 4730'. Release donut, pick up additional joints of 3. tubing and tag bottom. (Record depth.) PBTD should be at +/- 4905'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- 4. If fill, TIH with 3-7/8" bit and bit sub on 2-3/8" tubing and round trip to below perforations, cleaning out with air/mist. NOTE: When using air/mist, minimum mist rate is 12 bph. If scale is present, TIH with mill through perfs, TOOH.
- 5. TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary.

Land tubing at 4730'. ND BOP and NU WH. Pump off expendable check. Connect to casing 6. and circulate air to assure that expendable check has purnped off. Obtain pitot gauge up the tubing. If well will not flow on it's own, make swab run to SN. RD and MOL. Return well to production.

Recommended:

Bruce D Bown 6-1-98
Drilling Superintendent

Mary Ellen Lutey

Office - (599-4052)

Home - (325-9387)

Pager - (324-2671)