

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

079511-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Florance

9. WELL NO.

50

10. FIELD AND POOL, OR WILDCAT

Blanco Mesa Verde

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 15, T30N, R8W

12. COUNTY OR PARISH 13. STATE

San Juan

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)1. OIL ☐ GAS ☒ OTHER
WELL WELL2. NAME OF OPERATOR
Tenneco Oil Co.3. ADDRESS OF OPERATOR
1860 Lincoln St., Suite 1200 Denver, Colorado 802034. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface1667 FNL and 1916 FWL
Sec. 14, T30N, R8W

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

6459 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

1. MIRUPU and install BOP.
2. Run 7" packer to 4240 ± and pump 325 sxs of Class "A" neat cement.
3. Cut 7" casing at 3950 ± and lay down casing.
4. Place cement plug 50' into and 50' above 7" cut off stub.
5. Run freepoint indicator, cut 8 5/8" casing and lay down casing.
6. Place 100' plugs across 8 5/8" casing stub, 13 3/8" casing shoe at 360', and 225 sx
plug across Ojo- Fruitland from 2000' - 2400'.
7. Cut off casing head, place 20' surface plug in 13 3/8" casing and install dry hole
marker.
8. Clean up area.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Production Clerk

DATE

Oct 2, 1975

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side