

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. 078108	
2. NAME OF OPERATOR Sunray DX Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME -	
3. ADDRESS OF OPERATOR P. O. Box 1416, Roswell, New Mexico		7. UNIT AGREEMENT NAME -	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 660' FEL		8. FARM OR LEASE NAME New Mexico Federal "K"	
14. PERMIT NO.		9. WELL NO. 4	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5450' DF		10. FIELD AND POOL, OR WILDCAT Undesignated	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 34, T-30-N, R-15-W	
		12. COUNTY OR PARISH San Juan	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐Plug & Abandon ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Present PBTD @ 4642'.
2. Top of cmt behind 5 1/2" prod. csg. @ 4329'. 8 5/8" surf. csg @ 167' w/100 sx cmt circulated to surface. 5 1/2" prod. csg. @ 4360' w/62 sx cmt. 3 1/2" liner set @ 4660' w/top @ 4237 & used 30 sx cmt. Perfs @ 4610-11' & 4491'-4531'.
3. Load hole w/mud.
4. Cut off 5 1/2" csg at approx 4200'. Pull prod. csg. Keep hole loaded w/mud.
5. Place 35 sxs cmt plug in & out of 5 1/2" stub (4160-4220).
6. Set 17 sx cmt plug in & out of 8 5/8" surf csg (137'-197').
7. Set 10 sx cmt plug at surface.
8. Install dryhole marker.
9. Remove surface equipment and clean up location.

18. I hereby certify that the foregoing is true and correct

SIGNED B.F. Brawley B.F. Brawley TITLE District Engineer DATE 11-14-66

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

NOV 17 1966

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.