

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R-424.

5. LEASE DESIGNATION AND SERIAL NO.

078108

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

New Mexico Federal "K"

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 34, T-30-N, R-15-W

12. COUNTY OR PARISH 13. STATE

San Juan

New Mexico

SUNDRY NOTICES AND REPORTS ON

(Do not use this form for proposals to drill or to deepen or plug back to the surface. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Sunray DX Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 1416, Roswell, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

660' FSL & 660' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5450' DF

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐Plug & Abandon ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Present PBTD @ 4642'.

2. Top of cmt behind 5 1/2" prod. csg. @ 4329'. 8 5/8" surf. csg @ 167' w/100 sx cmt circulated to surface. 5 1/2" prod. csg. @ 4360' w/62 sx cmt. 3 1/2" liner set @ 4660' w/top @ 4237 & used 30 sx cmt. Perfs @ 4610-11' & 4491'-4531'.

3. Load hole w/mud.

4. Cut off 5 1/2" csg at approx 4200'. Pull prod. csg. Keep hole loaded w/mud.

5. Place 35 sxs cmt plug in & out of 5 1/2" stub (4160-4220).

6. Set 17 sx cmt plug in & out of 8 5/8" surf csg (137'-197').

7. Set 10 sx cmt plug at surface.

8. Install dryhole marker.

9. Remove surface equipment and clean up location.

RECEIVED

NOV 17 1966

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED B.F. Brawley B.F. Brawley TITLE District EngineerDATE 11-14-66

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

NOV 17 1966

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side