## UNITED STATES

# DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sulfary Not.	ices and Reports on Wells	•
	5. Lease Number	
Type of Well	SF-043260-A	
GAS	6. If Indian, A Tribe Name	ATT
	TIIDE NAME	
	7. Unit Agreeme	ent
Name of Operator		
BURLINGTON RESOURCES ON	12 P.S 1 1899	
RESOURCES OIL	& GAS COMPANY	
	OLL COMO DUVELL Name &	Nu
Address & Phone No. of Operat	tor Rederal F #1	
PO Box 4289, Farmington, NM	87499 (505) 326-9700 9. API Well No.	•
Location of Well Heaters of	30-045-08977	
Location of Well, Footage, Se 1565'FSL 1795'FEL, Sec.33, T-		
1.00 FEH, BEC.33, 1-		
	11. County and S	
	San Juan Co,	, N
Type of Submission	DICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Action	
_X_ Notice of Intent	Abandonment Change of Plans	
Subgament Banant	Recompletion New Construction	
Subsequent Report	Plugging Back Non-Routine Fracturing	
Final Abandonment	Casing Repair Water Shut off	
Final Abandonment	Altering Casing Conversion to Injection	
	Altering Casing Conversion to Injection X_ Other -	
Final Abandonment  Describe Proposed or Compl	Altering Casing Conversion to Injection X_ Other -	
	Altering Casing Conversion to Injection X_ Other -	
Describe Proposed or Compl	Altering Casing Conversion to Injection _X_ Other -  Leted Operations	
Describe Proposed or Compl  It is intended to repair t	Altering Casing Conversion to Injection X_ Other	
Describe Proposed or Compl	Altering Casing Conversion to Injection  X Other -  Leted Operations  The tubing on the subject well according to the	
Describe Proposed or Compl  It is intended to repair t	Altering Casing Conversion to Injection X_ Other	
Describe Proposed or Compl  It is intended to repair t	Altering Casing Conversion to Injection  X Other -  Leted Operations  The tubing on the subject well according to the	
Describe Proposed or Compl  It is intended to repair t	Altering Casing Conversion to Injection _X_ Other -  Leted Operations  The tubing on the subject well according to the .	
Describe Proposed or Compl  It is intended to repair t	Altering Casing Conversion to Injection _X_ Other -  Leted Operations  The tubing on the subject well according to the .	
Describe Proposed or Compl  It is intended to repair t	Altering Casing Conversion to Injection _X_ Other -  Leted Operations  The tubing on the subject well according to the .	
Describe Proposed or Compl  It is intended to repair t	Altering Casing Conversion to Injection _X_ Other -  Leted Operations  The tubing on the subject well according to the .	
Describe Proposed or Compl  It is intended to repair t	Altering Casing Conversion to Injection _X_ Other -  Leted Operations  The tubing on the subject well according to the .	
Describe Proposed or Compl  It is intended to repair t	Altering Casing Conversion to Injection _X_ Other -  Leted Operations  The tubing on the subject well according to the .	
Describe Proposed or Compl  It is intended to repair t	Altering Casing Conversion to Injection _X_ Other -  Leted Operations  The tubing on the subject well according to the .	
Describe Proposed or Compl  It is intended to repair t	Altering Casing Conversion to Injection _X_ Other -  Leted Operations  The tubing on the subject well according to the .	
Describe Proposed or Compl  It is intended to repair t     attached procedure	Altering Casing Conversion to Injection X Other -  Leted Operations  The tubing on the subject well according to the	
Describe Proposed or Compl  It is intended to repair t     attached procedure	Altering Casing Conversion to Injection _X_ Other -  Leted Operations  The tubing on the subject well according to the .	
Describe Proposed or Compl  It is intended to repair t     attached procedure  I hereby certafy that the	Altering Casing Conversion to Injection X Other	
Describe Proposed or Compl  It is intended to repair t     attached procedure	Altering Casing Conversion to Injection X Other	
It is intended to repair to attached procedure.  I hereby certify that the med sugar had held and held	Altering Casing Conversion to Injection	
It is intended to repair to attached procedure.  I hereby certify that the med sugar had held and held	Altering Casing Conversion to Injection X Other	

### Federal F#1

#### Dakota

## 1565' FSL & 1795' FEL

## Unit J, Section 33, T30N, R11W

Latitude / Longitude: 36° 45.9448'/ 107° 59.5633'

DPNO: 5081601

Tubing Repair Procedure

**Project Summary:** The Federal F #1 was drilled in 1964. The tubing was pulled 12/96 for a casing repair. A recent wireline check 1/99 could not get past 6614'. We propose to pull the tubing, check for fill, replace any worn or scaled tubing and add a controller for the plunger lift.

- Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- 3. The Dakota tubing is 2-3/8", 4.7#, J-55 set at 6729'. Release donut, pick up additional joints of tubing and tag bottom (record depth.) PBTD should be at +/- 6768'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- 4. If fill covers any perforations then TIH with 3-7/8" bit and a watermelon mill on 2-3/8" tubing to below perforations, cleaning out with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary. TOOH with tubing. **NOTE: When using air/mist, minimum mist rate is 12 bph.**
- 5. TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom. Run a broach on sandline to insure that the tubing is clear. Land tubing at approximately 6720'. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. If well will not flow on it's own, make swab run to SN. RD and MOL. Return well to production.

6. Production operations will install the plunger lift.

Recommended:

Departions Engineer / 1/29/99 Approved:

D :11:

ur Superintandant

Kevin Midkiff

Office - 326-9807

Pager - 564-1653