

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF-078144)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Fogelson 26

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

26-30N-11W

NMPM

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Beta Development Co.

3. ADDRESS OF OPERATOR

125 Petr. Club Plaza, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

1050/S 1000/E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5899' G.L.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☒

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)


REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to repair well as follows:

Rig up workover unit, circ. out drlg. mud. Set Baker Model "N" bridge plug in 4 1/2" csg. opposite Greenhorn section @ approx. 6600'. GIH w/4 1/2" packer on 2-3/8" tbg. & find top holes in csg. Set packer above all holes, pressure up back side of tbg. to 2000# to check all csg. back to surface. POH. Pick up drillable cement retainer, GIH w/tbg., set retainer above all csg. holes, squeeze w/350 sks 50/50 Pozmix Class "C" cement + 4% gel, or until pressure is 2000#. WOC 10 hrs. Drill out retainer w/3-7/8" bit on tbg, drill and CO to bridge plug. Pressure test all csg. to 2000#, repeat squeeze if necessary. Drill out bridge plug, CO to T.D. Land tbg., swab well in.



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Superintendent

DATE Feb. 10, 1969

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations of Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing; and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1983-O-885229

947-951



unpublished

Propose to repair well as follows:
 Rig up workover unit, circ. out drp. mud. Set Baker Model
 4" cas. opposite Greenhorn section approx. 6000'.
 top. find top holes in cas. Set Baker above all holes
 of top. to 2000' to check all cas. back to surface. Set
 cement retainer, 2 1/2" with 1" set retainer above all cas.
 2000' to 2000' cement + 4 1/2" gel, or until pressure
 will out retainer 2 1/2" bit on the drill and to drill
 rest of cas. to 2000'. Repeat squeeze if necessary. Drill
 2000' to 2000' land the 2 1/2" casing well in.

1000/2 1000/2

1000/2 1000/2

1000/2 1000/2