

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.
SP 000362-1

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Sunray Oil Company

3. ADDRESS OF OPERATOR
P. O. Box 1416, Roswell, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface
2032' PNL & 756' PNL

14. PERMIT NO.

15. ELEVATIONS (Show whether of RT, GR, etc.)
3232' DT

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
New Mexico Federal "P"

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Undesignated

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 30, T-30-N, R-15-W

12. COUNTY OR PARISH
Santa Fe

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLAN ☐
(Other) ☒ **Plug & Abandon**

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Present PNTD @ 4115'.
2. Top of cnt behind 5 1/2" prod. csg. @ 3400'. 8 5/8" surf. csg. @ 140' w/100 sx cnt circ. to surface. Open hole prod. zone @ 3960'-4115'.
3. Load hole w/mud.
4. Cut off 5 1/2" csg @ approx 3300'. Pull prod. csg. Keep hole isolated w/mud.
5. Place 50 sx cnt plug (3904'-4115') to cover perfs.
6. Place 12 sx cnt plug in & out of 5 1/2" stub (3270'-3330').
7. Set 17 sx cnt plug in & out of 8 5/8" surf csg (110'-170').
8. Set 10 sx cnt plug @ surface.
9. Instal dryhole marker.
10. Remove surface equipment and clean up location.

18. I hereby certify that the foregoing is true and correct

SIGNED **B. F. Brawley**

District Engineer

TITLE

DATE **11-14-66**

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

RECEIVED

NOV 17 1966

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.