

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON PERMITS

(Do not use this form for proposals to drill or to deepen or plug wells or to alter or repair.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Sunray DX Oil Company

3. ADDRESS OF OPERATOR
P. O. Box 1416, Roswell, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

790' FNL & 790' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5324 DF

5. LEASE DESIGNATION AND SERIAL NO.

SF 078107

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

New Mexico Federal "L"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 29, T-30-N, R-15-W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

Plug & Abandon

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Present PBTD @ 4140'.
2. Top cmt behind 5 1/2" prod. csg. @ 3800'. 8 5/8" surf csg set @ 410' w/225 sxs cmt circulated to surface. 5 1/2" prod csg set @ 4310' w/100 sxs cmt. Perfs @ 4050-4198'.
3. Load hole w/mud.
4. Cut off 5 1/2" prod csg @ approx. 3700'. Pull prod. csg. Keep hole loaded w/mud.
5. Place 35 sxs cmt plug (3880'-4240') to cover perfs.
6. Place 12 sxs cmt plug in & out of 5 1/2" stub (3670'-3730').
7. Set 17 sxs cmt plug in & out of 8 5/8" surf csg (380'-440').
8. Set 10 sxs cmt plug @ surface.
9. Install dryhole marker.
10. Remove surface equipment & clean up location.

RECEIVED

NOV 17 1966

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED B.F. Brawley TITLE District Engineer

DATE 11-14-66

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

NOV 17 1966

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side