


NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION



Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Federal ☐ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator El Paso Natural Gas Company 3. Address of Operator Box 990, Farmington, New Mexico 4. Location of Well UNIT LETTER M , 800 FEET FROM THE South LINE AND 1090 FEET FROM THE West LINE, SECTION 24 TOWNSHIP 30-N RANGE 9-W NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 5716' GL	7. Unit Agreement Name 8. Farm or Lease Name Riddle A 9. Well No. 3 (OWWO) 10. Field and Pool, or Wildcat Blanco Mesa Verde 12. County San Juan
--	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Squeeze, Case Cement, Perf & Fracture <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In order to increase production it is planned to workover and restimulate this well in the following manner:

Pull tubing, set a drillable bridge plug near the bottom of the 7" casing and pressure test to 1000 psi.
If tubing is stuck, cut off tubing approximately 100' below the 7" casing shoe, set a drillable cement retainer near the bottom of the 7" casing, squeeze the open hole with approximately 200 sacks of cement.
Pressure test the 7" casing with 1000 psi.
Isolate and squeeze cement any leaks. If leaks occur between 1320' and 2430' no block squeeze of the 7" annulus is planned.
If there are no leaks, perforate 2 squeeze holes at approximately 1320' and block squeeze the 7" annulus with approximately 125 sacks of cement.
Clean out or sidetrack and redrill to approximately 4800'.
Run a full string of 4 1/2" production casing and sufficient cement to tie in to the 7" casing shoe.
Selectively perforate and sand-water frac the Mesa Verde formation.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original signed,
Carl E. Matthews

SIGNED _____ TITLE **Petroleum Engineer** DATE **8-11-67**

APPROVED BY **Emory C. Arnold** TITLE **Asst Dir III** DATE **8-14-67**
CONDITIONS OF APPROVAL, IF ANY:

