

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1421
5. LEASE DESIGNATION AND SERIAL NO.

B.M. 09567-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS.

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR R & G Drilling Co., Inc.	8. FARM OR LEASE NAME Lunt
3. ADDRESS OF OPERATOR P.O. Box 327, Farmington, N.M. 87401	9. WELL NO. 66
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1690' FSL, 990' FWL Sec. 17-T30N-R13W 5.5 Co. N.Mex.	10. FIELD AND POOL, OR WILDCAT Basin Dakota
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5600' A.B.
	12. COUNTY OR PARISH San Juan
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUTOFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)PULL OR ALTER CASING
MULTIPLE COMPLETION
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:


WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)REPAIRING WELL
ALTERING CASING
ABANDONMENT*

X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Round trip 2" tbg. and replace 1 bad joint. String into packer. Seal assembly O.O.
2. Squeeze Dakota perms 6141-6052 with 35 sx to 2000 psi. Pull tbg. out of P.M. Spot 5 sx on top P.M.
3. Pull tbg. spotting 15 sx plug 5110-5260' and 15 sx plug 3750'-3900'.
4. Cut and pull 4 1/2 casing to 3500'.
5. Spot 35 sx plug 3550-3450', spot 53 sx plug 2900'-3050', spot 35 sx plug 1375'-1475', spot 15 sx plug 240'-195' spot 10 sx surface plug. Weld on plate 3' below surface.



RECEIVED

DEC 8 1976

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

U.S. GEOLOGICAL SURVEY

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side