Form approved.

Firm 3160-5 (November 1983) (Formerly 9-331)	UNITED S DEPARTMENT OF BUREAU OF LAND	THE INTERIO	SUBMIT IN TRIPLICAT (Other lastructions on verse side)	E. Bu Ex 5. LEASE	dget Burcau pires August DESIGNATION	No. 1004-0 31, 1985 AND SERIAL	
SUND	RY NOTICES AND m for proposals to drill or t se "APPLICATION FOR PER	REPORTS ON	N WELLS to a different reservoir. Deals. RECEIVED	6. IF IN	F-08122 DIAN. ALLOTTE Federal	E OR TRIBE N	AME
OIL A GAS WELL 2. NAME OF OPERATOR ARCO Oil and G	other as Company		NOV 1 0 1986	Hor 8. FARM Hor	seshoe seshoe	Gallup	
BUREAU OF LAND MANAGÉMEN  P. O. Box 1610, Midland, Texas 79702  Location of Well (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface  BUREAU OF LAND MANAGÉMEN  FARMINGTON RESOURCE AREA  1. Ocation of Well (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  Unit " G ",							
1650' FNL & 1750' FEL, Sec. 9  14. PERMIT NO.  15. ELEVATIONS (Show whether DF, RT, GR. etc.)  No API NO. Assigned 5462' GR					Sec 9-30N-16W  12. COUNTY OR PARISH 13. STATE  San Juan N M		
16. Not	Check Appropriate Bo	x To Indicate Nat	ure of Notice, Report, o	r Other Da			
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL	PULL OR ALTER CASING  PRACTURE TREAT  WHOUT OR ACIDIZE  ABANDON®		WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other)		REPAIRING ALTERING (	CASING	
(Other)	VPLETE: OPERATIONS (Mega!	y state all pertinent d	NOTE: Report rest Completion or Reco- etails, and give pertinent da- s and measured and true ver	upletion Repo	ort and Log for	te of startin	g any perti-
This well Plug	was plugged l  Interval	1/13/84 - 1 <u>Cement</u>	1/16/84 as fol	lows:			

Plug	<u>Interval</u>	<u>Cement</u>	
1	1046 - 1302	65 sx	Spotted plug to cover Gallup perfs 1235 - 1302.
2	645 - 745	25 sx	Squeezed 2 perforations at 745' to isolate the estimated TOC at 890'. Left a 100' cement plug inside the 5-1/2" casing.
3	49 - 139	30 sx	Squeezed 2 perforations at 139' to isolate the surface casing shoe at 89'. Left a 100' plug inside the 5-1/2" casing.
4	0 - 30	5 sx	Spotted a 5 sk plug at surface.

Welded a steel plate over the top & installed a dry 18. I hereby certify that the foregoing is true and correct 915-688-5672 TITLE Engr. Tech. Spec. (This space for Federal or State office use) APPROVED BY \_\_\_\_\_\_CONDITIONS OF APPROVAL, IF ANY: TITLE \_ Approved as to the rad logg. Liability under the FARMINGE surface restoration to a \*See Instructions on Reverse Side