Form 3160-5 (August 1999)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 200

5.	Lease Serial No.
	NMSF078336B

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				NMSF078336B	NMSF078336B		
				6. If Indian, Allottee o	6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRI	7. If Unit or CA/Agre	7. If Unit or CA/Agreement, Name and/or No.					
1. Type of Well	8. Well Name and No. BARRETT LS 2	8. Well Name and No. BARRETT I S 2					
Oil Well 🛛 Gas Well 📋 Oth		9. API Well No.					
Name of Operator     BP AMERICA PRODUCTION	MARY CORLEY E-Mail: corleyml@bp.c	om	30-045-10641-0	30-045-10641-00-S1			
3a. Address       3b. Phone No.         P. O. BOX 3092       Ph: 281.360         HOUSTON, TX 77253       Fx: 281.366			area code)	10. Field and Pool, or Exploratory BLANCO MESAVERDE			
4. Location of Well (Footage, Sec., T	1)		11. County or Parish, and State				
Sec 19 T31N R9W NWNE 079 36.88884 N Lat, 107.81792 W			SAN JUAN COUNTY, NM				
12. CHECK APPE	ROPRIATE BOX(ES) T	O INDICATE NATU	RE OF NOT	CE, REPORT, OR OTHE	R DATA		
TYPE OF SUBMISSION	TYPE OF ACTION						
	☐ Acidize	☐ Deepen		Production (Start/Resume)	■ Water Shut-Off		
Notice of Intent     ■	☐ Alter Casing	☐ Fracture Tre	at 🗖	Reclamation	■ Well Integrity		
☐ Subsequent Report		■ New Constr	action $\square$	Recomplete	☐ Other		
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Ab	and Abandon				
_	☐ Convert to Injection	☐ Plug Back	Back				
If the proposal is to deepen directions Attach the Bond under which the wo following completion of the involved testing has been completed. Final At determined that the site is ready for f BP America respectfully reque the attached procedure.	rk will be performed or provid d operations. If the operation ro pandomment Notices shall be fi inal inspection.) est permission to perform	e the Bond No. on file with esults in a multiple comple led only after all requirem	n BLM/BIA. Rec ction or recomplet ents, including re	uired subsequent reports shall be ion in a new interval, a Form 316 clamation, have been completed,	tiled within 30 days		
14. Thereby certify that the foregoing is	Electronic Submission	A PRODUCTION CO.	sent to the Far	mington			
Name (Printed/Typed) MARY CC	DRLEY	Title	AUTHORIZE	D REPRESENTATIVE			
Cincolne (Flore)	Submission)	Date	09/26/2002				
Signature (Electronic		OR FEDERAL OR		ICE USE			
20 34					OCT 15 2002		
Approved By /e/ Jim Lov	8(C)	Title			Date   3 2002		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

## Barrett LS 2 API #: 30-045-10641 T31N R9W Sec19

**Reason for work:** The NMOCD has requested BP to repair intermediate casing/bradenhead leak on this well.

- 1. Check anchors. MIRU workover rig.
- 2. Check and record tubing, casing, and bradenhead pressures.
- 3. Blow down well. Kill well with 2% KCL water ONLY if necessary.
- 4. Nipple down WH. NU BOPs and diversion spool with 3" outlets and 3" pipe to the blow tank. Pressure test BOPs to 500 psi.
- 5. Run 4 1/2" casing scraper to 2000'.
- 6. RIH and set CIBP at 2000'.
- 7. Back off 4 1/2" casing at depth about 1800'.
- 8. RIH with 7" casing scraper to top of 4 1/2" casing.
- 9. Set 7" retrievable bridge plug or CIBP at top of 4 1/2" casing.
- 10. If necessary, RU Schlumberger and run CBL/VDL/GR/CCL from 1800' to surface.
- 11. PU perforating guns. Perforations depth will be determined later after having the CBL result.
- 12. Attempt to circulate or establish injection rate.
- 13. Mix and pump cement as per design. WOC.
- 14. Clean out cement to top of bridge plug. Test casing to 500 psi.
- 15. Clean out or pull bridge plug.
- 16. Run 4 1/2" casing with DV tool and screw in to the top of 4 1/2" casing in the hole.
- 17. Mix and pump cement as per design. WOC
- 18. Install tubing spool.
- 19. RIH and clean out cement, CIBP at 2000' and fill if necessary to PBTD at 6262' with air package. Blow well dry.
- 20. RIH with 2 3/8" tubing and land at 6140'. Test tubing to 500 psi while RIH.
- 21. Swab water from tubing with the sandline.
- 22. RU slickline unit. Run gauge ring for 2-3/8" tubing. Pull plug. RD slickline unit.
- 23. ND BOP's and NU WH. Return well to production.

## Barrett LS 2

Sec 19, T31N, R9W API#: 30-045-10641

