UNITED STATES

DEPARTMENT OF THE INTERIOR

| BUREAU OF LAND MANAGEMENT | AECEIVED BLMED |
|--|--|
| Sundry Notices and Reports on Wel | |
| · · · · · · · · · · · · · · · · · · · | 24 PM |
| 1. Type of Well GAS | 070 5. Least Mmber 6. Is Tribe Name |
| | 70 |
| 2. Name of Operator BURLINGTON | Unit Agreement Name & Number |
| OIL & GAS COMPANY | E 18 1300 |
| 3. Address & Phone No. of Operator | Well Name & Number |
| 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M | Quinn #7 Quinn #7 API Well No. 30-045-10801 |
| 4. Location of Well, Footage, Sec., T, R, M 810'FNL 990'FEL, Sec.17, T-31-N, R-8-W, NMPM | 10. Field and Pool Mesaverde 11. County and State San Juan Co, NM |
| 12 CUPOF ADDRODDIAND DOV NO TANDICAND NAMEDO OF MONTON | DEPOSE OF STATE OF ST |
| 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE Type of Submission Type of Ac | |
| X Notice of Intent Abandonment | Change of Plans |
| | New Construction |
| | Non-Routine Fracturing |
| Casing Repair | Water Shut off |
| Final Abandonment Altering Casing X_ Other - | Conversion to Injection |
| 13. Describe Proposed or Completed Operations | |
| It is intended to repair the tubing on the subject attached procedure. | ct well according to the |
| | |
| 14. I hereby certify that the foregoing is true and | correct. |
| Signed Signed (MEL6) Title Regulator | y Administrator_Date 11/18/98 |
| (This space for Federal or State Office use) | TLW |
| APPROVED BY /S/ Duane W Spencer Title CONDITION OF APPROVAL, if any: | Date <u>DEC 6 1908</u> |
| Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to me United States any false, fictitious or fraudulent statements or representations as to any me | ake to any department or agency of the matter within its jurisdiction. |

Quinn #7

Blanco Mesaverde

Unit A, Sec. 17, T-31-N, R-8-W Latitude / Longitude: 36°54.14340' / 107°41.54940' Recommended Tubing Repair Procedure 10/23/98

Project Notes: This well hasn't been pulled since completion in 1958. The lease operator reported that slickline could not broach the 2-3/8" tubing to run a choke and test the tubing for plunger-lift installation. Seven tight spots were found in the tubing. Unfortunately, the slickline ticket could not be found.

NOTE: ALL DEPTHS ARE MEASURED FROM KB. KB to GL was 11'.

- 1. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Prior to moving in rig, make one-call and then verify rig anchors and dig pit.
- 2. MIRU workover rig. NU relief line and blow well down (kill with 2% KCL water only if necessary). ND WH and NU BOP. Test and record operation of BOP rams. Replace any WH valves that do not operate properly. Test secondary seal and install or replace if necessary.
- 3. **Mesaverde, 2-3/8", 4.7#, J-55 tubing set at 6025'.** Release donut, pick up additional joints of tubing and tag bottom, recording the depth. PBTD should be at +/- 6052'. TOOH and stand back 2-3/8" tubing. Visually inspect tubing for corrosion, and replace any bad joints. Check tubing for scale and notify Operations Engineer if it is present.
- 4. PU & TIH with 4-3/4" bit, bit sub, and watermelon mill on 2-3/8" tubing and round trip to PBTD, cleaning out with air/mist. **NOTE: When using air/mist, mist rate must not be less than 12 bph.** Speak with Operations Engineer, and if necessary, determine the best way to remove scale from the casing and perforations. LD bit, bit sub, and mill.
- 5. TIH with one joint of 2-3/8" tubing with expendable check, F-nipple (one joint off bottom), then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing. Replace any bad joints. CO to PBTD with air/mist.
- 6. PU above the top Mesaverde perforation at **5316'** and flow the well naturally, making short trips for clean-up when necessary.
- 7. Land tubing at **5950'**. Obtain pitot gauge from casing and report this gauge. Broach the upper ½ of the production tubing. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. If well will not flow on its own, make swab run to SN. RD and MOL. Return well to production.

Recommended: M. & Auty Approved: Biture Dorke

Operations Engineer: Mary Ellen Lutey Office 599-4052

Pager 324-2671