State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

	Sundry Notices and Re	spores on werrs	
1 The of Wall			# (assigned by OCD) 30-045-20934
1. Type of Well GAS			Lease Number
		6.	State Oil&Gas Lease # E-1196-9-NM
2. Name of Operator		7.	Lease Name/Unit Name
BURLINGTON			
OIL & GAS COMPANY		_	EPNG Com A
3. Address & Phone No. of Operat		8.	Well No. 2A
PO Box 4289, Farmington, NM 87499 (505) 326-9700		9.	Pool Name or Wildcat
4. Location of Well, Footage, Se	oc T R M	10	Mesaverde Elevation:
890'FNL 1190'FWL, Sec.32, T-3			in the state of th
Type of Submission	Type of Act	ion	
X Notice of Intent		Change of Pl	ans
		New Construc	
Subsequent Report	Plugging Back		
Final Abandonment	Casing Repair Altering Casing	Water Shut o	
Final Abandonment	X Other -	_ conversion c	o injection
It is intended to repair t attached procedure			
		ECEIVE NOV 2 4 1998	
		ii con di	70%
Residence		ा ं अ	
SIGNATURE SALAND	(MEL6) Regulatory A	Administrator	November 18, 1998
			TLW
(This space for State Use)			
ORIGINAL SIGNED BY CHARLIE Approved by	ET. PERRIN TitleDEPUTY OIL & G	AS INSPECTOR, DIST.	MOV 2 4 199

EPNG Com A #2A

Mesaverde 890'FNL, 1190' FWL

Unit D, Section 32, T-31-N, R-8-W

Latitude / Longitude: 36° 51.5597' / 107° 42.1728'

DPNO: 48741A **Tubing Repair Procedure**

- Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental 1. regulations. Test rig anchers and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in <u>DIMS/WIMS</u>. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow 2. well down and kill with 2% KCL water if necessary. ND wellhead and NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace install as necessary.
- Mesaverde, 2-3/8", 4.7# J-55 tubing is set at 5965'. Release donut, pick up additional joints of 3. tubing and tag bottom. (Record depth.) PBTD should be at +/- 6080'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale/paraffin build up and notify Operations Engineer.
- If fill, TIH with 4-3/4" bit, bit sub and watermelon mill on 2-3/8" tubing and round trip to below 4. perforations, cleaning out with air/mist. NOTE: When using air/mist, minimum mist rate is 12 bph. If scale is present, contact Operations Engineer to determine methodology for removing scale from casing and perforations.
- TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one 5. joint off bottom then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary.
- Land tubing at ± 5890 '. ND BOP and NU WH. Pump off expendable check. Connect to casing 6. and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow up the tubing, make swab run to SN. RD and MOL. Return well to production.

Recommended: M.E. Surjuger Operations Engineer

Bruce D. Borys 10: 35-959 Drilling Superintendent

Operations Engineer:

Mary Ellen Lutey

Office - (599-4052) Home - (325-9387)

Pager - (324-2671)